



Dŵr Cymru
Welsh Water

PLA0073810



LEGEND(Representative of most common features)

Waste networks:		
Foul chamber		Outfall
Surface water chamber		Lamphole
Combined chamber		Storm Overflow
Combined sewer overflow		Rising main
Special purpose chamber		Gravity sewer
Treatment works		Private sewer
Pumping station		Private sewer subject to Sect. 104 adoption agreement
NB: Sewer symbol colour indicates the type.		Private Sewer Transfer
RED - Combined		Lateral Drain
GREEN - Surface Water		Inspection Chamber
BROWN - Foul		
Purple - Former S24 sewers (for indicative purposes only)		

Notes:

Whilst every reasonable effort has been taken to correctly record the pipe material of DCWW assets, there is a possibility that in some cases pipe material (other than Asbestos Cement or Pitch Fibre) may be found to be asbestos cement (AC) or Pitch Fibre (PF). It is therefore advisable that the possible presence of AC or PF pipes be anticipated and considered as part of any risk assessment prior to excavation.

Dŵr Cymru Cymuned (the Company) gives this information as to the position of its underground apparatus by way of general guidance only and on the understanding that it is based on the best information available and is not warranted as to its correctness in the event of excavations or other works made in the vicinity of the Company's apparatus. The error of location of apparatus is not warranted and any excavations made entirely on your own. The information which is supplied by the Company is done so in accordance with statutory requirements of sections 103 and 109 of the Water Industry Act 1991 which is based upon the best information available and, in particular, but without prejudice to the generality of the foregoing, it should be noted that the records that are available to the Company may not disclose the existence of water mains, service pipes, drains, water or sewer pipes and any excavations made entirely on your own. It is therefore advisable that the possible presence of AC or PF pipes be anticipated and considered as part of any risk assessment prior to excavation.

Service pipes are not generally shown but their presence should be anticipated.

**EXACT LOCATIONS OF ALL APPARATUS
TO BE DETERMINED ON SITE.**

Reproduced by permission of the Ordnance Survey on behalf of
HMSSO. © Crown copyright and database right 2017.
All rights reserved.
Ordnance Survey Licence number 100019534

Map Ref: 333856,349704
Map scale: 1:750
Printed by: David Hubbard
Printed on: 03 Jul 2023

