



The North Eastern elevation of Unit 5 taken from the roundabout.



The Northern elevation of Unit 5 and the North Eastern elevation (the gable end) of the adjoining Unit 3 taken from atop The Hill.



The North Eastern elevation of Unit 3 taken from The Hill.



Above and below ... the Northern elevation of Unit 3 taken from on top of The Hill. Note the significant storm damage...





The storm ravaged South Western corner of Unit 3 and its gable end. Note the sleeper walls.



Above and below shows the storm damaged South facing elevation of Unit 3 leading to Unit 5.



The above photograph shows the South Western corner of Unit 3 (the right hand side) and the South facing elevation of the same leading to the South Western elevation (gable end) of adjoining Unit 5.



The above photographs show the inside of Unit 3 looking towards the North Eastern gable end (left) and the South Western gable end (right). Note the steel plates around the walls, fitted to 'protect' the sleeper walls.



The above two photographs are from inside Unit 3 and show the steel plates and the sleeper walls behind.



The above two photographs are close ups of the corroded steel plates that make up the bottom section of the walls throughout Unit 3. They show salt slag residue (the cause of all the steel corrosion) emanating from behind them. Please note that although we are asking McAuliffe to dispose of ALL the steelwork, we are going to dispose of both the salt slag residue and the old railway sleepers.



The South Western corner of Unit 3 (from inside) showing the storm damage suffered in December 2021 (Arwen) and February 2022 (Eunice) and the accumulation of broken fibre cement roof/cladding sheets piled up on the floor. The two storms made a good fist at starting the Demolition works for us!!




The above photo shows the South facing internal elevation of Unit 5. Please note the concrete panels.



The North Eastern (gable end) internal elevation of Unit 5 showing the roller shutter door &c.



A close up of the South Western (gable end) elevation of Unit 5 showing the abovesaid concrete panels that make up the lower section of the walls. Please note the concrete panels are to be set aside for us to dispose of.



A close up of the same section of wall in Unit 5 which shows the evidence of pigeon infestation...