

Window Schedule

Ty Llwyd
Glyn Ceiriog
LL20 7EH

Ref: 2018

Date of Inspection: August 16, 2023

Surveyor: D Bates

Photos

Ref	Photo	Comments
1		No frame repairs Glazing heritage double glazing 12mm Chamfered timber glazing beads to hold in new units. Decoration
2		No frame repairs metal frame Remaining single glazed Re-putty Decoration
3		No frame repairs Re-glazed double glazing 12mm heritage Timber chamfered bead external Decoration
4		No frame repairs Heritage double glazing Timber glazing bead Decoration

Ref	Photo	Comments
5	 A photograph of a window with a white frame and a small transom above it. The window is set in a white wall. A wooden board is leaning against the right side of the window.	No frame repairs Re-glazed double glazing 12mm heritage Timber chamfered bead external Decoration Drip rail required
6	 A photograph of a window with a white frame and a small transom above it. The window is set in a white wall. A yellow tool is visible on the sill.	No frame repairs Heritage double glazing Timber glazing bead exteriors Decoration
7	 A photograph of a window with a white frame and a small transom above it. The window is set in a white wall. A wooden board is leaning against the left side of the window.	No frame repair Heritage double glazing Timber ext beads chamfered Decoration
8	 A photograph of a window with a white frame and a small transom above it. The window is set in a white wall. A wooden board is leaning against the left side of the window.	New stub cill Repair left right lower part of frame see next item

Ref	Photo	Comments
9		Frame requires repair Splice new piece of Redwood
10		Stub cill repair New redwood timber to be planted
11		No frame repairs Heritage glazing Timber chamfered glazing bead Decoration
12		No frame repairs Heritage glazing Timber chamfered glazing bead Decoration

Ref	Photo	Comments
13		No frame repairs Heritage glazing Timber chamfered glazing bead Decoration
14		No frame repairs Heritage glazing Timber chamfered glazing bead Decoration
15		No frame repairs Heritage glazing Timber chamfered glazing bead Decoration
16		frame repairs to bottom see next item timber splice Heritage glazing Timber chamfered glazing bead Decoration

Ref	Photo	Comments
17		Timber splice repair
18		No frame repairs Glazing beads to be re-used Heritage glazing Decoration
19		No frame repairs Heritage glazing Timber chamfered glazing bead Decoration
20		No frame repairs Heritage glazing Timber chamfered glazing bead Decoration

Ref	Photo	Comments
21		Heritage glazing Timber chamfered glazing bead Decoration See next item for cill repair
22		cill to be timber spliced in redwood
23		20mm rebate. Total depth of glazing bar 40mm
24		15mm set to frame. From back edge

Ref	Photo	Comments
25	 Minster™ Privacy Level 2	Glazing pattern for Bathroom windows. Numbers 6&7