



Dŵr Cymru
Welsh Water

Sewer Plan



LEGEND(Representative of most common features)

Waste network:	Foul chamber	Outfall
Surface water chamber	Combined sewer chamber	Storm Overflow
Combined sewer overflow	Special purpose chamber	Rising main
Treatment works	Pumping station	Gravity sewer
Private sewer subject to Sect. 104 adoption agreement	Private Sewer Transfer	Lateral Drain
Inspection Chamber		

Notes:

Whilst every reasonable effort has been taken to correctly record the pipe material of DCWW assets, there is a possibility that in some cases pipe material (other than Asbestos Cement or Pitch Fibre) may be found to be asbestos cement (AC) or Pitch Fibre (PF). It is therefore advisable that the possible presence of AC or PF pipes be anticipated and considered as part of any risk assessment prior to excavation.

Dŵr Cymru Cylfyngedig (the Company) gives this information as to the position of its underground apparatus by way of general guidance only and on the understanding that it is based on the best information available and is not warranted as to its correctness in the event of excavations or other works made in the vicinity of the company's apparatus. The error of location of apparatus before carrying out any excavations will be entirely on you. The information which is supplied by the Company is done so in accordance with statutory requirements of sections 103 and 109 of the Water Industry Act 1991 which is based upon the best information available and, in particular, but without prejudice to the generality of the foregoing, it should be noted that the records that are available to the Company may not include the existence of water mains, service pipes, drains, lateral drains or disposal mains and any unrecorded apparatus laid before 1 September 1986 or, if they are, the potential thereof that their position and depth may not be accurate. It must be understood that the furnishing of this information is entirely without prejudice to the provisions of the New Roads and Street Works Act 1991 and the Company's rights to be compensated for any damage to its apparatus.

Service pipes are not generally shown but their presence should be anticipated.

**EXACT LOCATIONS OF ALL APPARATUS
TO BE DETERMINED ON SITE.**

Reproduced by permission of the Ordnance Survey on behalf of
HMSSO. © Crown copyright and database right 2017.
All rights reserved.
Ordnance Survey Licence number 100019534

Map Ref: 333086,352976
Map scale: 1:3500
Printed by: Natalie Walmsley
Printed on: 25 Nov 2021

