



LEGEND(Representative of most common features)

	Foul chamber		Outfall
	Surface water chamber		Lamphole
	Combined chamber		Storm Overflow
	Combined sewer overflow		Rising main
	Special purpose chamber		Gravity sewer
	Treatment works		Private sewer
	Pumping station		Private sewer subject to Sect. 104 adoption agreement
NB: Sewer symbol colour indicates the type.			Private Sewer Transfer
RED - Combined			Lateral Drain
GREEN - Surface Water			Inspection Chamber
BROWN - Foul			
Purple - Former S24 sewers (for indicative purposes only)			

Notes:

Whilst every reasonable effort has been taken to correctly record the pipe material of DCWW assets, there is a possibility that in some cases pipe material (other than Asbestos Cement or Pitch Fibre) may be found to be asbestos cement (AC) or Pitch Fibre (PF). It is therefore advisable that the possible presence of AC or PF pipes be anticipated and considered as part of any risk assessment prior to excavation.

Dŵr Cymru Cylfyngedig (the Company) gives this information as to the position of its underground apparatus by way of general guidance only and on the understanding that it is based on the best information available and is not warranted as to its correctness in the event of excavations or other works made in the vicinity of the Company's apparatus. The error of locating apparatus enables carrying out any excavations with safety on site. The information which is supplied by the Company is given in accordance with statutory requirements of sections 103 and 109 of the Water Industry Act 1991 which is based upon the best information available and, in particular, but without prejudice to the generality of the foregoing, it should be noted that the records that are available to the Company may not disclose the existence of water mains, service pipes, sewer, lateral drains or other apparatus and any excavation apparatus (as defined in Section 109(1)(b) of the Water Industry Act 1991) which may be present in the ground. It is the responsibility of the excavator to ensure that the location of any such apparatus is correctly identified and that the necessary precautions are taken to avoid damage to it. It is not the responsibility of the Company to ensure that the location of any such apparatus is correctly identified and that the necessary precautions are taken to avoid damage to it. It is not the responsibility of the Company to ensure that the location of any such apparatus is correctly identified and that the necessary precautions are taken to avoid damage to it.

Service pipes are not generally shown but their presence should be anticipated.

**EXACT LOCATIONS OF ALL APPARATUS
TO BE DETERMINED ON SITE.**

Reproduced by permission of the Ordnance Survey on behalf of
HMSSO. © Crown copyright and database right 2017.
All rights reserved.
Ordnance Survey Licence number 100019534

Map Ref: 337835,349389
Map scale: 1:2500
Printed by: Walmsley Natalie
Printed on: 15 Oct 2020

