




Sewer Plan PLA0060494



LEGEND(Representative of most common features)



Notes:

Whilst every reasonable effort has been taken to correctly record the pipe material of DCWW assets, there is a possibility that in some cases pipe material (other than Asbestos Cement or Pitch Fibre) may be found to be asbestos cement (AC) or Pitch Fibre (PF). It is therefore advisable that the possible presence of AC or PF pipes be anticipated and considered as part of any risk assessment prior to excavation.

De-Cimur Cynglynging (The Company) gives this information as to the position of its underground apparatus by way of general guidance only and is not the strict understanding that it is based on the best information available and is not warranty as to its correctness is relied upon in the event of excavations or other works made in the vicinity of the company's apparatus. The usual of locating apparatus before carrying out any excavations rests entirely on you. The information which is supplied by the Company, is done so in accordance with statutory requirements of sections 198 and 199 of the Water Industry Act 1991 and the related provisions of the Water Resources Act 1989. The Company cannot be held responsible for any damage or loss of property or injury to persons or animals caused by the use of the information. In the event of the Company being notified of any change in the location of the apparatus, it should be noted that the records that are available to the Company may not disclose the existence of a water main, service pipe, sewer, lateral drain or disposal main and any associated apparatus laid before 1 September 1990, or if they do, they may not be accurate. The Company does not accept any liability for any damage or loss of property or injury to persons or animals caused by the use of the information. It must be understood that the furnishing of this information is entirely without prejudice to the provision of the National and Street Works Act 1991 and the Company's right to be compensated for any damage to its apparatus.

Service sites are not necessarily shown but their existence should be anticipated.

EXACT LOCATIONS OF ALL APPARATUS
TO BE DETERMINED ON SITE.

Reproduced by permission of the Ordnance Survey on behalf of
HMSO. © Crown copyright and database right 2017.
All rights reserved.
Ordnance Survey Licence number 100019534

Map Ref: 333322,350432
Map scale: 1:750
Printed by: Natalie Walmsley
Printed on: 19 Oct 2021