

## List of Plates:

### AC1

Plate 1: River Clywedog (receptor) - looking west upstream with flooded ox-bow lake on left where site outfall is located (07-01-2014).

Plate 2: Blocked drain leading to outfall to ox-bow lake located North of SS11-06-1 (10-12-2014).

Plate 3: French drain Interceptor NW Corner SS11-07-1 (10-12-2014).

Plate 4: French Drain (SS11-07-1) NW Boundary – Looking North (10-12-2014).

Plate 5: Looking East along the site Northern boundary towards SW2/SS11-05-1. Track has flowing water from a leaking water main on site flowing off site onto neighbouring farm land (10-12-2014).

Plate 6: Leaking Water Service on Northern boundary track SS11-05-01 (10-12-2014).

Plate 7: Leaking Water Service on Northern boundary track SS11-05-01 (10-12-2014).

### AC2

Plate 8: BH2 - Training Centre – Window sample (approx 1m sample liner length 26-11-13)

Plate 9: BH23 Garage – Window sample (approx 1m sample liner lengths 09-12-2013)

Plate 10: TP1 South of Garage (29-11-2013)

Plate 11: TP6 Example of Material for Treatment (28-11-2013)

Plate 12: TP10 West of Training Centre (27-11-2013)

Plate 13: MW11-08B Groundwater by Garage (12-12-2013)

### AC3

Plate 14: Looking East from Outfall SS11-03-01 onto pond located in SW Corner (13-12-2013)

Plate 15: Contamination on pond water surface from outfall SS11-03-01 onto pond located in SW Corner (13-12-2013)

Plate 16: Contamination on pond water surface from outfall SS11-03-01 onto pond located in SW Corner (13-12-2013)

### AC4

Plate 17: Blocked Culvert upstream of Bedwell Tip (12-12-2013)

Plate 18: Blocked culvert -only one side flowing by Bedwell Tip (12-12-2013)

Plate 19: Blocked Culvert in eastern area of Bedwell Brook at site boundary by entrance to site (12-12-2013)

Plate 20: Leachate Outbreak besides outfall pipe into Brook at Bedwell Tip (12-12-2013)

Plate 21: Leachate Outbreak besides outfall pipe into Brook at Bedwell Tip (12-12-2013)

Plate 22: Staining in brook bank by tip and marked as RB1 on plan (12-12-2013)

Plate 23: Bedwell Brook Sediment SD2 (10-12-2013)

Plate 24: Bedwell Brook Sediment SD2 (10-12-2013)

Plate 25: Bedwell Brook Sediment SD2 (10-12-2013)

Plate 26: Bedwell Brook Sediment SD2 (10-12-2013)

Plate 27: Bedwell Brook Sediment SD4 (10-12-2013)

Plate 28: Waste on Bedwell Brook Banks (10-12-2013)

Plate 29: Area B West TP45 (04-12-2013)

AC1

Plate 1: River Clywedog (receptor) - looking west upstream with flooded ox-bow lake on left where site outfall is located (07-01-2014).



Plate 2: Blocked drain leading to outfall to ox-bow lake located North of SS11-06-1 (10-12-2014).



Plate 3: French drain Interceptor NW Corner SS11-07-1 (10-12-2014).



Plate 4: French Drain (SS11-07-1) NW Boundary – Looking North (10-12-2014).



Plate 5: Looking East along Northern boundary towards SW2/SS11-05-1. Track has flowing water from a leaking water main on site flowing off site onto neighbouring farm land (10-12-2014).



Plate 6: Leaking Water Main on Northern boundary track SS11-05-01 (10-12-2014).



Plate 7: Leaking Water Service on Northern boundary track SS11-05-01 (10-12-2014).



AC2

Plate 8: BH2 - Training Centre – Window sample (approx 1m sample liner length 26-11-13)



Plate 9: BH23 Garage – Window sample (approx 1m sample liner lengths 09-12-2013)



Plate 10: TP1 South of Garage (29-11-2013)



Plate 11: TP6 – Example of Material for Treatment (28-11-2013)



Plate 12: TP10 West of Training Centre (27-11-2013)



Plate 13: MW11-08B Groundwater by Garage (12-12-2013)



AC3

Plate 14: Looking East from Outfall SS11-03-01 onto pond located in SW Corner (13-12-2013)



Plate 15: Contamination on pond water surface from outfall (13-12-2013)



Plate 16: Contamination on pond water surface from outfall (13-12-2013)



AC4

Plate 17: Blocked Culvert upstream of Bedwell Tip (12-12-2013)



Plate 18: Blocked culvert -only one side flowing by Bedwell Tip (12-12-2013)



Plate 19: Blocked Culvert in eastern area of Bedwell Brook at site boundary by entrance to site (12-12-2013)



Plate 20: Leachate Outbreak besides outfall pipe into Brook at Bedwell Tip (12-12-2013)



Plate 21: Leachate Outbreak besides outfall pipe into Brook at Bedwell Tip (12-12-2013)



Plate 22: Staining in brook bank by tip and marked as RB1 on plan (12-12-2013)



Plate 23: Bedwell Brook Sediment SD2 (10-12-2013)




Plate 24: Bedwell Brook Sediment SD2 (10-12-2013)



Plate 25: Bedwell Brook Sediment SD2 (10-12-2013)



Plate 26: Bedwell Brook Sediment SD2 (10-12-2013)



Plate 27: Bedwell Brook Sediment SD4 (10-12-2013)



Plate 28: Waste on Bedwell Brook Banks (10-12-2013)



Plate 29: Area B West TP45

