


P/2017/0758

Plas Mostyn Bach - condition 9 - validation of remediation of works.

Photo evidence of works, email from Dandy's topsoil and receipts for soil and grass seed.
(I was unable to upload separately the details for Dandy`s due to download name/ref not being compatible)

Photos above showing hardcore for patio and path, wall built to depth required around the lawn area for importation of clean soil to raise the lawn area up 600mm,







Photos of the trial hole to 600mm depth and photo that shows the permanent patio, path, and drive to the other (right) side of the raised garden. The area naturally inclines up from the barn to drive and from end of barn to patio, step up from path to patio due to this. Areas created from the removal of the old milking parlour.