

MASONRY CRACKING IN CHANCEL END (EASTERN) WALL DUE TO FOUNDATION SETTLEMENT.

ST DAVIDS CHURCH, RHOSLLANERCHRUGOG – RECORD PHOTOGRAPHS OF DISTRESS





CRACKING AND DISTORTION WESTERN END WALL AND RETURN AT REAR





SPLITS IN ENTRANCE PORCH FLOORS