

P/2024/0103 Brunett farm SY13 3BA

Good Morning Simon,

Please find attached door drawings.

I will follow this email with some photographs to demonstrate the difficulty of giving door frame inset measurements due to the walls being quite out of plumb. All we can suggest is that the door frames will be installed to provide a suitable fixing point for the doors and they will not protrude the external brickwork. this could be 20mm or 100mm depending on where one measures.

as it was with the windows, a sample door can be made and installed for inspection if this would be a more straightforward solution.

Kind Regards,

Tom