

Heritage Impact Statement

8 Hill Street Cefn Mawr.

This application is to replace the existing windows and install conservation roof windows.

The property is within the conservation area in Cefn Mawr. It is attached on one side and partially attached by a porch on the other side. It is in a state of disrepair. The frontage is covered with a poor render finish with a partial brick porch. The roof is a slate and the windows are uPVC.

The windows are to be replaced and 2No. conservation roof windows are to be installed on the front elevation.