

Heritage Impact Statement Regarding repair to Existing Wall attached to Pate Gate and Vehicular Entrance to Property.

1/




Current Condition of Wall – Leaning substantially towards Roadway

2/ Wall is Coursed and 4m +/- to be removed and straightened on a new foundation using Lime mortar and washed sand mix -internal wall is of random design. Intention is to improve structural integrity without any change to walls appearance



3/Current Overview Tree removed already



Final Entranceway with separation between Garden and Parking Area shown. Existing Gate to Pate Gate will be improved Edwardian themed design.

