

Supporting Document Summary

Pre-existing	No change to file or details
Revised	No change to file, details updated
New	New file added to this version
Deleted	File removed from this version

Proposal Name	Replace Sash Windows
Reference	PP-11379010
Version Number	1
Submission Date	19/07/2022
Attachments	
Document Name	Design and access statement
Document Description	Sash windows specification
Status	New
Submission Date	05/07/2022
Submission Method	Uploaded to storage
File Name	22377 Rev C - Quotation.pdf
File Type	application/pdf
File Size (bytes)	520775

Document Name	The location plan
Document Description	Title Deed plan of area affected by the change
Status	New
Submission Date	18/07/2022
Submission Method	Uploaded to storage
File Name	Screenshot_20220718-230220_Office.jpg
File Type	image/jpeg
File Size (bytes)	865809
Document Name	Additional plans
Document Description	Joiner has advised condition of current windows are beyond restoration due to water damage. Rotten wood. Broken cords. Windows do not open.
Status	New
Submission Date	18/07/2022
Submission Method	Uploaded to storage
File Name	20220714_104311.jpg
File Type	image/jpeg
File Size (bytes)	2509497

Document Name	Other relevant information
Document Description	Joiner has advised condition of current windows are beyond restoration due to water damage. Rotten wood. Broken cords. Windows do not open.
Status	New
Submission Date	18/07/2022
Submission Method	Uploaded to storage
File Name	20220714_104317.jpg
File Type	image/jpeg
File Size (bytes)	2913131

Document Name	Other relevant information
Document Description	Joiner has advised condition of current windows are beyond restoration due to water damage. Rotten wood. Broken cords. Windows do not open.
Status	New
Submission Date	18/07/2022
Submission Method	Uploaded to storage
File Name	20220714_104322.jpg
File Type	image/jpeg
File Size (bytes)	2955263

Document Name	Other relevant information
Document Description	Joiner has advised condition of current windows are beyond restoration due to water damage. Rotten wood. Broken cords. Windows do not open.
Status	New
Submission Date	18/07/2022
Submission Method	Uploaded to storage
File Name	20220714_104503.jpg
File Type	image/jpeg
File Size (bytes)	2284746
Document Name	Other relevant information
Document Description	Joiner has advised condition of current windows are beyond restoration due to water damage. Rotten wood. Broken cords. Windows do not open.
Status	New
Submission Date	18/07/2022
Submission Method	Uploaded to storage
File Name	20220714_104526.jpg
File Type	image/jpeg
File Size (bytes)	2321820

Document Name	Other relevant information
Document Description	Joiner has advised condition of current windows are beyond restoration due to water damage. Rotten wood. Broken cords. Windows do not open.
Status	New
Submission Date	18/07/2022
Submission Method	Uploaded to storage
File Name	20220714_105050.jpg
File Type	image/jpeg
File Size (bytes)	3123236
Document Name	The location plan
Document Description	Title Deed plan of property affected.
Status	New
Submission Date	19/07/2022
Submission Method	Uploaded to storage
File Name	Lot_10_025345 71 Erddig Road Wrexham Official Copy (Title Plan) - CYM772252.PDF
File Type	application/pdf
File Size (bytes)	193371

Document Name	Section - Proposed
Document Description	Sash & Glazing Bar sections
Status	New
Submission Date	19/07/2022
Submission Method	Uploaded to storage
File Name	22377 Bar Sections.pdf
File Type	application/pdf
File Size (bytes)	2596888
Document Name	Detail Drawing
Document Description	Detail Drawings
Status	New
Submission Date	19/07/2022
Submission Method	Uploaded to storage
File Name	CG-BFSS_PQ (Combined).pdf
File Type	application/pdf
File Size (bytes)	152178

Document Name	Detail Drawing
Document Description	Heritage Unit detail
Status	New
Submission Date	19/07/2022
Submission Method	Uploaded to storage
File Name	HERITAGE UNITS.pdf
File Type	application/pdf
File Size (bytes)	167493

Document Name	Heritage impact statement
Document Description	Heritage statement attached.
Status	New
Submission Date	19/07/2022
Submission Method	Uploaded to storage
File Name	Heritage Statement.docx
File Type	application/vnd.openxmlformats-officedocument.wordprocessingml.document
File Size (bytes)	13143