

# PHOTOGRAPHIC RECORD

## Descriptive Proposals


THE LONG PULL (PH)

5 Chester Street

Wrexham

LL13 8BD

November 202



**GROUND FLOOR**



G01. Bar Servery replaced. Fixed seating removed. New timber flooring and cosmetic redecoration works.



G02. Bar Servery replaced. Fixed seating removed. New timber flooring and cosmetic redecoration works.



G03. Bar Servery and Backfitting removed and replaced with new in similar location.



G04. Fixed seating removed. New timber flooring and cosmetic redecoration works.



G05. Fixed seating removed. New carpet flooring and cosmetic redecoration works.



G06. Bar Servery replaced. Fixed seating removed. New timber flooring and cosmetic redecoration works.



G07. New fixed seating along wall. New carpet and cosmetic redecoration works.



G08. New fixed seating along wall. New carpet and cosmetic redecoration works. New opening formed to structural wall.



G09. New fixed seating along wall. New carpet and cosmetic redecoration works. New opening formed to structural wall.



G10. General cosmetic redecoration.




G11. New fixed seating along wall. New carpet and cosmetic redecoration works.



G12. Toilets removed and relocated. This area is to be opened up in to the public area with the opening formed within the existing wall on the right.



G13. Toilets removed and relocated. This area is to be opened up in to the public area with the opening formed within the existing wall.



G14. This area is to be opened up in to the public area with the opening formed within the existing partition wall.



G15. Existing toilet area to be rearranged and refurbished with entirely new finishes.



G16.




G17.



G18. Existing Yard area to be enclosed to form new toilet facilities.



G19. Existing Yard area to be enclosed to form new toilet facilities. Existing windows closed off and adapted to suit new layout.




## BASEMENT



B01.



B02.



B03.



B04.



B05.



B06.




B07.



B08.



B09.



FIRST FLOOR



F01. Evidence of significant leaks. Proposals include for repairs to roofs.



F02.



F03. General refurbishment in order to reinstate accommodation to upper levels.



F04. General refurbishment in order to reinstate accommodation to upper levels.



F05.



F06. Existing modern kitchen partition to be removed and new opening kitchen installed.



F07. General refurbishment in order to reinstate accommodation to upper levels.



F08. New kitchen installed.



F09.



F10. Flat roof to be extended over existing Yard area.



F11. General refurbishment in order to reinstate accommodation to upper levels.



F12.



F13. General refurbishment in order to reinstate accommodation to upper levels.



F14. Existing modern partition to be removed (right).



F15.



F16. General refurbishment in order to reinstate accommodation to upper levels.



F17.




F18.



F19. General clear out and roof repairs for use at a later date.



F20.



**SECOND FLOOR**



S01. General refurbishment in order to reinstate accommodation to upper levels.



S02.



S03.



S04. General refurbishment in order to reinstate accommodation to upper levels.



S05.



S06.



S07. General refurbishment in order to reinstate accommodation to upper levels.



S08.



S09. General refurbishment in order to reinstate accommodation to upper levels.



S10.



S11.