


INDICATIVE



NOTES

GENERAL NOTES: ==

CITY ORANGEVALE SURVEY HAS BEEN PLOTTED ONTO AN OS BASE PLAN, THEREFORE MIDLAND SURVEY ACCEPTS NO RESPONSIBILITY FOR ITS ACCURACY.

THIS DRAWING HAS BEEN PRODUCED WITH A PLOT SCALE ACCURACY OF 1:200

SERVICE COVERS INDICATED WHERE VISIBLE. PIPE INVERTS / DETAILS SURVEINED FROM SURFACE. DEPTHS ONLY. GENERALLY DAMAGED COVERS AND COVERS WITH INVERTS WILL NOT BE LIFTED

THREE STREETS SHOULD BE CONFIRMED BY THIS SURVEY IF CRITICAL.

OVERHEAD CABLES ARE INDICATED (USE REMOTE SURVEY METHODS AND ARE SUBJECT TO SEASONAL VARIATION) AND SHOULD BE TREATED AS APPROXIMATE.

SERVICE COVERS LOCATED UNDER PARKED VEHICLES/MOBILE STRUCTURES MAYBE OMITTED

BURIED SERVICE COVERS WILL NOT BE INDICATED.

TOPOGRAPHICAL SURVEY/UTILITY KEY :-

[illegible]

UTILITY SURVEY KEY:

	HATCHED AREA		POUL SENDER
	BOREHOLE		STORM SENDER
	CPT		COMBINED SENDER
	TRIAL PIT		DUCTS
	HAND PIT		CABLE TELEVISION
	WINDOW SAMPLE		DATA CABLE
			TELECOM CABLE
			GAS PIPE
			UNIDENTIFIED SERVICE
			OTHER
			CTV
			TL
			TL
			TRAFFIC LIGHT
			VENT
			OFFSET PILE
			F
			F
			GAUGE LINES
			P
			P
			PIPE
			AT
			ASSUMED ROUTE
			TAKEN FROM RECORDS

DISCLAIMER :

Electronic techniques have been used in the thousands of underground searches. The results show that information obtained should be carried out to confirm service identification, positions and particularly depth. There are considerable problems in carrying out underground searches. No information cannot be guaranteed.

This method of survey does not differentiate between the dead and services. The location of all services shown on this drawing may not include the location of all public services that may cross the site, therefore the relevant service drawings should be obtained from the appropriate utility company and used in conjunction with this drawing.

Private service pipes and cables in highways are not shown, but there presence should be anticipated.

Additional below ground structures or obstructions not shown on this drawing may be identified. Reference should be made to the following:-

- 1. The Highway Act 1980
- 2. The Highways Act 1980
- 3. The Highways Act 1980

Excavations in the vicinity of services should be carried out with due diligence. Ref: HGS47 document avoiding dangers from underground services

Notes: 1. The factors that may influence the quality of the data collected are:-

- a. The nature of the ground conditions, primarily the soil type and the method of search.
- b. The nature of the ground conditions, primarily the soil type and the method of search.

on site.

UTILITY NOTES

ALL BURIED MANHOLES HAVE BEEN PLOTTED ON USING CCTV CHAINAGE, THEREFORE POSITIONS SHOULD BE TREATED AS GUIDE ONLY.



MIDLAND SURVEY LTD

HEAD OFFICE

Tel: 01928 810811 Fax 01928 810812
E-Mail: mail@midlandsurvey.co.uk

www.midlandsurvey.co.uk

Client	Geography	Information
Client	Florida, Miami, Dade, Middle	

TR#	GCTV DRAINAGE SURVEY
-----	----------------------

Date	AUGUST 2021	Revisions
------	-------------	-----------

Scale 1:200000

Dwg No 39629 - 0

Surveyor	AB
----------	----

Checked	R.P.
---------	------

TOPOGRAPHICAL (LAND) SURVEYORS / UTILITY SURVEYORS
BUILDING MEASUREMENT SURVEYORS / 3D LASER SCANNING

©Copyright Midland Survey Ltd. Reproduction of this information is prohibited without written authorisation from Midland Survey Ltd.