

# ARBORICULTURAL SITE SUPERVISION

Tree Solutions

Planning Ref No: P/2017/0134  
Developer: Gower Homes Ltd  
Site Address: Boozey Fields, Griffiths Rd,  
Stansty, Wrexham  
Site Agent: J10 Planning  
Visit Date: 26 March 2018  
Arboricultural Supervisor: A. Henderson

5, Orchard Close,  
Chester, CH2 2JD

T: +44 (0)1244 389114  
F: +44 (0)7075 167890  
M: +44 (0)7766 774508

info@tree-solutions.co.uk  
www.tree-solutions.co.uk

## Site Supervision

Has tool-box talk on all tree protective measures been undertaken?

Yes ☒ No ☐

Was all tree protective fencing in accordance with approved plans & AMS?

Yes ☒ No ☐

Was all tree protective fencing in place?

Yes ☒ No ☐

Was any debris noticed within Total Exclusion Zones?

Yes ☐ No ☒

Are any special works scheduled for the coming building period?

Yes ☐ No ☒

Details: NB -> T1 APPEARS STRESSED & IN DECLINE

WITH DEAD WOOD & DIEBACK IN CROWN - REPORT THIS TO WCBC

Are any amendments proposed to plans?

Yes ☐ No ☒

Details: FENCING AROUND T1 & T2 ERECTED TO FULL EXTENT OF

RPA. THEY WILL BE RECALIBRED WITH GROUND PROTECTION BOARDS INSTALLED.

Signed:

(For and on behalf of Tree Solutions Ltd)

Signed:

(Gower Homes Ltd)

## Circulation:

|                          |                                     |
|--------------------------|-------------------------------------|
| Tree Solutions Ltd       | <input checked="" type="checkbox"/> |
| Developer Head Office    | <input checked="" type="checkbox"/> |
| Site Agent               | <input checked="" type="checkbox"/> |
| Local Planning Authority | <input checked="" type="checkbox"/> |

Our Ref: 15/AIA/WXM/165

**P/2017/0134 - Boozey Fields, Griffiths Road, Stansty**  
**Site Inspection Photographs - 26/03/2018**



**Photo 1 - Tree protective fencing erected to full extend of RPA of T1 & T2. Fencing will be realigned to secondary position and ground protection boards laid when scaffolding is due to be erected for plots 49 & 50**



**Photo 2 - Tree protective fencing erected to timber posts concreted in place to prevent movement**



**Photo 3 - Fencing around T1**



**Photo 4 - Fencing in correct location around T3.**



**Photo 5 - Fencing around RPA of T3**



**Photo 6 - Fencing around full extent of RPA of T3 & concreted in place to prevent movement**



**Photo 7 - Fencing around full extent of RPA of T3**



**Photo 8 - Fencing erected along RPA of G4 & in accordance with approved Arboricultural Method Statement**



**Photo 9/10 - Heras fence panels fixed to timber posts with ant-tamper bolts & post concreted into ground to prevent any movement during development works**