

MEMORANDUM

From:	Service Manager Environment	To:	Head of Community Well-being and Development
Our Ref:	P/2015/0866	Your Ref:	P/2015/0866
Date:	3 December 2015		

Location: O. S Grid Ref: 3310 3550 Alyn View, Mold Road, Cefn y Bedd

Development: Erection of one detached dormer bungalow with associated parking on land to rear of Alyn View.

I refer to your consultation 16 November 2015 in respect of the above.

The site is located on a busy classified highway (A541 Mold Road) subject to a 40mph speed limit.

It is proposed to utilise the existing access adjacent to Cherry Cottage. The access is less than 3m wide and does not permit the simultaneous passage of vehicles.

It is considered that this may lead to a conflict of vehicular movements at the shared access.

Any vehicle leaving the site blocks the whole access. Given that the main road is so busy any vehicle may have to sit in the access for some time waiting for a gap in the traffic.

Any vehicle wishing to enter the access will have to wait on the highway if the access is blocked. As this is a heavily trafficked road with vehicles travelling up to, and sometimes beyond, the 40 mph speed limit there is serious potential for rear end collision at the access.

I therefore recommend that the application is refused for the following reason:

The inadequate access width of the access does not permit the simultaneous passage of vehicles and is likely to cause vehicles to stop on the highway with consequent risk of additional danger to all users of the road.



Service Manager Environment

1/1