01 / 3000 Lifting Floorboards




NOTES

Lifting Floorboards:


- If boards will not lift easily, check construction and do not force them.
- If necessary to cut a board, cut along the side of a joist, using an appropriate saw. Ensure there are no pipes or cables below the boards. When re-laying the board support the end on a batten secured into the side of the joist. Ensure board is returned to its original position.
- Lift board as detailed in detail 01.

NB: Only floor boards away from the edge of the rooms to be lifted as to not disturb skirtings or architraves where applicable.

02 / 3000 Temporary access boarding installation As Proposed



02 / 3000 Temporary access boarding installation As Proposed



NOTES

Temporary access boarding installation
Youngman Board Reference Image



- Board spans to be confirmed with structural engineers. Span should aim to be as minimal as possible.
- Dimensions to be reviewed to suit existing structure
- Fixings to be confirmed

Notes

1. Any dwg format drawing is to be read in conjunction with and at the scale of the accompanying pdf.
2. Where colours other than black or grey are used, the drawing must be plotted in colour.
3. For status 'C' (Construction) drawings all dimensions are to be checked on site by the contractor, scaling is for Local Authority purposes only.
4. Unless otherwise indicated, all dimensions are in millimeters.
5. All information on this drawing is to be read in conjunction with the relevant Donald Insall Associates specification and trade contractors' drawings and information by specialists.
6. In the event of any discrepancy, please contact us immediately.
7. This drawing may contain survey information by others and is to be used solely for the purposes for which it was issued.
8. These are uncontrolled documents issued for information purposes only. If you have any queries regarding the drawings, please contact DIA immediately.
9. Please note DIA cannot be held responsible for any errors arising from changes made to an uncontrolled dwg file.

© 2019 DONALD INSALL ASSOCIATES LTD

Drawing Status

- **F** Feasibility
- **S** Sketch Design
- **P** Planning
- **B** Building Control
- **D** Design Development
- **M** Measurement
- **T** Tender
- **C** Construction
- **R** Record

Rev	Date	Dwn	Auth	Revision
1	01-08-2025	AVD	CSH	Drawing updates
0	25-07-25	AVD	CSH	Initial Issue

Donald Insall Associates
Chartered Architects and Historic Building Consultants

Y Becws, Pool Lane
Conwy LL32 8PZ
(+44) 01492 592 378
conwy@insall-architects.co.uk

Erddig Hall, Wrexham

Opening Up Works
Details 01

Project	No
NTWFS.02	3000

Scale (A3)	Status	Revision
1: NTS	P	1