



GROUND FLOOR
WINDOW LOCATION PLAN



1ST FLOOR
WINDOW LOCATION PLAN


NOTES:

THIS DRAWING IS THE PROPERTY OF McCORMICK ARCHITECTURE LTD AND COPYRIGHT IS RESERVED BY THEM. THE DRAWING IS NOT TO BE COPIED OR DISCLOSED BY OR TO ANY UNAUTHORISED PERSONS WITHOUT THE WRITTEN CONSENT OF McCORMICK ARCHITECTURE LTD.
McCORMICK ARCHITECTURE LTD TAKE NO RESPONSIBILITY FOR ANY DIMENSIONS OBTAINED BY SCALING FROM THIS DRAWING. IF NO DIMENSION IS SHOWN THE RECIPIENT MUST ASCERTAIN THE DIMENSION SPECIFICALLY FROM THE ARCHITECT OR BY SITE MEASUREMENT. CONTRACTORS TO CHECK ALL DIMENSIONS ON SITE AND TO REPORT ANY DISCREPANCIES. ELECTRONIC ISSUE VERSIONS OF THIS DRAWING ARE NOT TO BE CHANGED BY RECIPIENTS OR 3rd PARTIES.


NOTE:
THIS DRAWING IS FOR PLANNING APPLICATION PURPOSES ONLY

WINDOW TYPE A

INTERNAL



EXTERNAL




PROPOSED WORKS:

EXISTING METAL FRAMED WINDOW TO BE REFURBISHED TO INCLUDE THE FOLLOWING WORK:


- EXISTING METAL WINDOW FRAME TO BE REPAIRED AND MADE GOOD TO MATCH EXISTING.

WINDOW TYPE B/ B1

INTERNAL



EXTERNAL



PROPOSED WORKS:

WINDOW TYPE B

EXISTING METAL FRAMED WINDOW TO BE REFURBISHED TO INCLUDE THE FOLLOWING WORK:

- EXISTING METAL WINDOW FRAME TO BE REPAIRED AND MADE GOOD TO MATCH EXISTING.
- SECONDARY GLAZING TO BE INSTALLED INTERNALLY TO FUTURE DETAILS.


WINDOW TYPE B1

EXISTING METAL FRAMED WINDOW TO BE REFURBISHED TO INCLUDE THE FOLLOWING WORK:

- EXISTING METAL WINDOW FRAME TO BE REPAIRED AND MADE GOOD TO MATCH EXISTING.
- SECONDARY GLAZING TO BE INSTALLED INTERNALLY TO FUTURE DETAILS.

WINDOW TYPE C/C1

INTERNAL



EXTERNAL



PROPOSED WORKS:

WINDOW TYPE C

EXISTING METAL FRAMED WINDOW TO BE REFURBISHED TO INCLUDE THE FOLLOWING WORK:

- EXISTING METAL WINDOW FRAME TO BE REPAIRED AND MADE GOOD TO MATCH EXISTING.
- SECONDARY GLAZING TO BE INSTALLED INTERNALLY TO FUTURE DETAILS.


WINDOW TYPE C1

EXISTING METAL FRAMED WINDOW TO BE REFURBISHED TO INCLUDE THE FOLLOWING WORK:


- EXISTING METAL WINDOW FRAME TO BE REPAIRED AND MADE GOOD TO MATCH EXISTING.
- OBSCURE GLAZING PANES TO REPLACED WITH NEW CLEAR SINGLE GLAZING. COLOURED GLAZING TO PERIMETER TO BE RETAINED.
- SECONDARY GLAZING TO BE INSTALLED INTERNALLY TO FUTURE DETAILS.

WINDOW TYPE D/D1

INTERNAL



EXTERNAL



PROPOSED WORKS:

WINDOW TYPE D

EXISTING METAL FRAMED WINDOW TO BE REFURBISHED TO INCLUDE THE FOLLOWING WORK:

- EXISTING METAL WINDOW FRAME TO BE REPAIRED AND MADE GOOD TO MATCH EXISTING.
- SECONDARY GLAZING TO BE INSTALLED INTERNALLY TO FUTURE DETAILS.


WINDOW TYPE D1

EXISTING METAL FRAMED WINDOW TO BE REFURBISHED TO INCLUDE THE FOLLOWING WORK:


- EXISTING METAL WINDOW FRAME TO BE REPAIRED AND MADE GOOD TO MATCH EXISTING.
- OPENABLE WINDOWS TO BE FREED TO INCLUDE ALL WORKING PARTS SO THAT THE WINDOWS OPERATE FREELY.
- OBSCURE GLAZING PANES TO REPLACED WITH NEW CLEAR SINGLE GLAZING. COLOURED GLAZING TO PERIMETER TO BE RETAINED.
- SECONDARY GLAZING TO BE INSTALLED INTERNALLY TO FUTURE DETAILS.

WINDOW TYPE E

INTERNAL



EXTERNAL



PROPOSED WORKS:

EXISTING METAL FRAMED WINDOW TO BE REFURBISHED TO INCLUDE THE FOLLOWING WORK:

- SECONDARY GLAZING TO BE INSTALLED INTERNALLY TO FUTURE DETAILS.

WINDOW TYPE F

INTERNAL



EXTERNAL




PROPOSED WORKS:

EXISTING TIMBER FRAMED WINDOW TO BE REFURBISHED TO INCLUDE THE FOLLOWING WORK:


- EXISTING TIMBER WINDOW FRAMES TO BE REPAIRED AND MADE GOOD TO MATCH EXISTING.
- WINDOW FRAME TO BE PRIMED AND PAINTED TO MATCH EXISTING.
- SECONDARY GLAZING TO BE INSTALLED INTERNALLY TO FUTURE DETAILS.

WINDOW TYPE G

INTERNAL



EXTERNAL



PROPOSED WORKS:

EXISTING TIMBER FRAMED WINDOW TO BE REFURBISHED TO INCLUDE THE FOLLOWING WORK:

- EXISTING TIMBER WINDOW FRAMES TO BE REPAIRED AND MADE GOOD TO MATCH EXISTING.
- OPENABLE WINDOWS TO BE FREED TO INCLUDE ALL WORKING PARTS SO THAT THE WINDOWS OPERATE FREELY.
- IRONMONGERY TO BE CLEANED AND REFITTED TO OPERATE FREELY.
- OBSCURE GLAZING REPLACED WITH NEW CLEAR SINGLE GLAZING.
- WINDOW FRAME TO BE PRIMED AND PAINTED TO MATCH EXISTING.
- SECONDARY GLAZING TO BE INSTALLED INTERNALLY TO FUTURE DETAILS.

McCORMICK
ARCHITECTURE
THE MOORINGS, ROWTON BRIDGE ROAD,
CHRISTLETON, CHESTER. CH3 7AE
TEL: 01244 332020
email:info@mccormick-architecture.co.uk
web:www.mccormick-architecture.co.uk

Client:
GARY CONWAY

Project:
FORMER PRESBYTERIAN CHURCH
HOLT

Detail:
PLANNING DRAWING
PROPOSED EXISTING WINDOW TREATMENT

Status:
PRELIMINARY

Drawn By:	Date:	Scale:
FOR APPROVAL	06/12/23	NTS @ A1
Checked By:	Date:	Signature:
PM	09/01/24	P. McCORMICK
Job No:	Drg No:	Revision:
4235/1	A(300)03	