APPENDIX 2 – PHOTOGRAPHIC RECORD

Woodland Compartment Photos



Compartment W1 from permissive path



Compartment W1 from permissive path




Compartment W2 from W8 looking east across Glanyrafon Brook



Compartment W2 from W8 looking east across Glanyrafon Brook



Compartment W2 and W8 from permissive path in north section of W8




Compartment W4 and clearing



Compartments W3, W4 and W7 looking along Glanyrafon Brook



Compartment W4 clearing looking east towards W1 and W3



Compartment W5 looking south from permissive path



Compartment W5 looking north along Glanyrafon Brook




Compartment W6 looking west towards boundary



Compartment W7 and permissive path



Compartment W7 looking towards W6 and area of willow carr



Compartment W8 ash plantation and permissive path



Compartment W8 ash plantation and permissive path



Compartment W8 ash plantation and permissive path



Compartment W8 ash plantation and permissive path

Significant Trees along the PRoW and Eastern Boundary of Woodland W1 – South to North (reading left to right in order across page)



South extent of W1 alder 144



South east of woodland W1 at PRoW



Oak 154



Stile at PRoW to south oak 154 and sycamore 156



Ash 159



Oak 238, sycamore 164

		
Oak 238 (February 2022 storm damage)	W1 looking south to stile towards Hafod Road	W1 looking north back to railway
		
Sycamore 924	Sycamore 924	Crab apple 915

mdlandscape

6 Kinderton Close | High Legh | Knutsford| Cheshire | WA16 6LZ | mdlandscape@btinternet.com | 07710 498231

		
Sycamore 908	Oak 905	Ash 893(A)
		
Ash 893(A) to left, ash 891 to right	Ash 891 to left	Flailed edge to W1

		
Hornbeam 870, ash 876, small-leaved lime 879, ash 882	Ash 863, oak 864 and 865	Beech 862
		
Beech 862 to corner, wild cherry 1129(G) to right	Wild cherry 1129(G), sycamore 1111	Sycamore 1108

		
Cluster of dead trees at 1105, Oak 1098 with previous scaffold branch failure and decay	Oak 1067	Oak 938
		
Gap between 938 oak left and 941 ash right	Ash 941 to right	Ash 941 to left, beech 943 and 944 to right

mdlandscape

6 Kinderton Close | High Legh | Knutsford| Cheshire | WA16 6LZ | mdlandscape@btinternet.com | 07710 498231



North east boundary of woodland (W1) and existing PRoW



View of south of woodland from PRoW near Hafod Road



Oak 143 at Hafod Road

Other significant trees in woodland W1 and trees with notable defects near PRoW



Field maple 616(A) in W1



Sycamore 149 to south section of W1



Oak 143 small FFB bracket at base of tree

mdlandscape

Chartered Member of the Landscape Institute | Landscape Institute Registered Practice | Arboricultural Association Registered Practice

6 Kinderton Close | High Legh | Knutsford| Cheshire | WA16 6LZ | mdlandscape@btinternet.com | 07710 498231

		
Sycamore 164 bifurcate and fused stems in W1	*Ganoderma* sp bracket to base of ash 893(A)	*Fistulina hepatica* (beefsteak fungus) bracket to oak 1098