
P/2025/0409 - CAE COCH, GOLLY, ROSSETT, WREXHAM, LL12 0AL 21.07.2025

Please see below a basic sketch of the current drainage, there is no evidence of any other drains, manholes or anything that suggests the foul water goes anywhere else other than the ditch



Below are photos of the manholes with the direction of the pipework highlighted



Red arrow - flow direction
Blue arrow - septic tank location



Kitchen sink gulley



Left arrow - Kitchen sink gulley
Middle arrow – IC by side door
Right arrow - towards septic tank
(the septic tank is in a terrible condition, lid is broken, weeds growing out of it)



Top arrow - flowing from septic tank.
Bottom arrow - flowing towards garage manhole



Bottom arrow - flow from septic tank
Left arrow - flow towards road
Right arrow - rain water from barn roof into same manhole (see next picture)



Left arrow - from septic tank
Bottom arrow - from barn rain water
Top arrow- towards road ditch



View from road looking back at the barn (top arrow)
Middle arrow - pipe from barn manhole flow towards road ditch.
Left arrow - pipe direction towards ditch



Right arrow - flow from barn manhole. Middle arrow - flow towards ditch.