Date Submitted: 27/02/2024 04:45 PM
Submitted By: renewables@heatforce.co.uk

ASHP & Cylinder Survey Form

Customer/Property Details

Client	City Energy
FOR SURVEY ISSUES OR QUERIES PLEASE CALL THE SURVEYOUR BELOW	
Surveyor	Andy Magee - 07816603295
Customers Name	Mr robinson
Address	4 Wynne terrage
Postcode	LI207et
Photos of Outside of Property	
	52.931557, -3.189113 27/02/2024 04:38 PM

ASHP & Cylinder Survey Form

Is asbestos suspected in present materials?	No
If yes, please detail below:	
Electric Meter Type	Standard
Existing Heating	ERH
Stopcock Location	Kitchen
Photo of Stopcock	

HEATFORCE
Fireplaces / Bathrooms / Heating / Renewables

ASHP & Cylinder Survey Form

Photos of Existing Heating (Include Databadges)	
	52.931715, -3.189181 27/02/2024 04:26 PM

ASHP & Cylinder Survey Form

Location / GPS	
	Lat: 52.931688165940834 Long: -3.189209498076132
	27/02/2024 04:26 PM

ASHP Details

ASHP Position	Garden
Floor Mount/Wall Mount	Floor Mount

HEATFORCE
Fireplaces / Bathrooms / Heating / Renewables

ASHP & Cylinder Survey Form

ASHP Position Photo(s)	

HEATFORCE
Fireplaces / Bathrooms / Heating / Renewables

ASHP & Cylinder Survey Form

	
	52.931734, -3.189146 27/02/2024 04:37 PM
Pipe Run Details from Heat Pump to cylinder	Run up outside into rear bedroom onto skirting board to airing cupboard
Would you like to provide further details/photos/video of pipe route?	No
Notes	
Photos	
Video	
Confirmed Clearances OK	Yes
Position Agreed with Customer	Yes
Condensate Termination	Gully

ASHP & Cylinder Survey Form

Condensate Termination Photo(s)	
	52.931732, -3.189183 27/02/2024 04:37 PM
Amount of Pipe Needed (15mm) In Meters	75
Amount of Pipe Needed (22mm) In Meters	30
Amount of Pipe Needed (28mm) In Meters	24
Amount of Talon Trunking Required (15mm) Lengths	2
Amount of Talon Trunking Required (22mm) Lengths	1

Cylinder Details

HEATFORCE
Fireplaces / Bathrooms / Heating / Renewables

ASHP & Cylinder Survey Form

Cylinder Position	Airing cupboard
Cylinder Position Photo(s)	
	52.931676, -3.189213 27/02/2024 04:28 PM
Slim/Standard/Well Master	Standard
A/C Depth	800
A/C Width	850
A/C Height	1500
A/C Door Height	1400
A/C Door Width	740
Adequate Access to get Cylinder to Selected Location (E.G Up Stairs)	Yes

HEATFORCE
Fireplaces / Bathrooms / Heating / Renewables

ASHP & Cylinder Survey Form

Checked Cylinder Clearances	Yes
Existing Water Supply	Mains
Position Agreed with Customer	Yes
PRV Termination Description	Run across skirting board with heating flow and returns

Radiator Details

How many rooms require radiators?	7
Room 1	Bedroom 1
Radiator Location(s) Photo (Include all Radiators)	
Room 2	Landing


HEATFORCE
Fireplaces / Bathrooms / Heating / Renewables

ASHP & Cylinder Survey Form

Radiator Location(s) Photo (Include all Radiators)	
Room 3	Bathroom

HEATFORCE
Fireplaces / Bathrooms / Heating / Renewables

ASHP & Cylinder Survey Form

Radiator Location(s) Photo (Include all Radiators)	
Room 4	Bedroom 2


HEATFORCE
Fireplaces / Bathrooms / Heating / Renewables

ASHP & Cylinder Survey Form

Radiator Location(s) Photo (Include all Radiators)	
Room 5	Kitchen

HEATFORCE
Fireplaces / Bathrooms / Heating / Renewables

ASHP & Cylinder Survey Form

Radiator Location(s) Photo (Include all Radiators)	
Room 6	Dining Room


HEATFORCE
Fireplaces / Bathrooms / Heating / Renewables

ASHP & Cylinder Survey Form


Radiator Location(s) Photo (Include all Radiators)	
Room 7	Lounge

HEATFORCE
Fireplaces / Bathrooms / Heating / Renewables

ASHP & Cylinder Survey Form

Radiator Location(s) Photo (Include all Radiators)	

ASHP & Cylinder Survey Form

	
Room 8	
Radiator Location(s) Photo (Include all Radiators)	
Room 9	
Radiator Location(s) Photo (Include all Radiators)	
Room 10	
Radiator Location(s) Photo (Include all Radiators)	
Room 11	
Radiator Location(s) Photo (Include all Radiators)	

HEATFORCE
Fireplaces / Bathrooms / Heating / Renewables

ASHP & Cylinder Survey Form

Room 12	
Radiator Location(s) Photo (Include all Radiators)	
Room 13	
Radiator Location(s) Photo (Include all Radiators)	
Room 14	
Radiator Location(s) Photo (Include all Radiators)	
Room 15	
Radiator Location(s) Photo (Include all Radiators)	
Room 16	
Radiator Location(s) Photo (Include all Radiators)	
Room 17	
Radiator Location(s) Photo (Include all Radiators)	
Room 18	
Radiator Location(s) Photo (Include all Radiators)	
Room 19	
Radiator Location(s) Photo (Include all Radiators)	
Room 20	
Radiator Location(s) Photo (Include all Radiators)	
Room 21	
Radiator Location(s) Photo (Include all Radiators)	
Room 22	
Radiator Location(s) Photo (Include all Radiators)	
Room 23	
Radiator Location(s) Photo (Include all Radiators)	
Room 24	
Radiator Location(s) Photo (Include all Radiators)	
Room 25	

ASHP & Cylinder Survey Form

Radiator Location(s) Photo (Include all Radiators)	

Additional Notes/Photos

Additional Notes/Photos Required?	No
Notes	
Additional photos	

Signoff

Customer Pre-Requirements? (E.g. Move Furniture)	Yes
Customer Pre-Requirement Description	Customer to remove garden bank before install.customer to move furniture. Customer aware that floor board will be lifted and cut(vanished bedroom floor
Confirmed with Customers that there will be some exposed pipework	Yes
Installation Notes	Install ashp in garden under kitchen window.condensate to gully. Run flow and returns up outside into bedroom across skirting it a/c
Surveyors Name	Andrew Magee
	27/02/2024 04:42 PM
Surveyors Signature	
Customers Name	Mr Robinson
Customers Signature	
	27/02/2024 04:44 PM

ASHP & Cylinder Survey Form

Form Locations

