Pontcysyllte Aqueduct Access Improvements

Existing Situation

Drawing number: 10058635-AUK-XX-XX-DR-LA-0010-P2
FOR PLANNING
Date: APRIL 2024
Drawn by: AA
Checked by: EC

Trevor Basin
Visitor Centre
Grass
Bin
Bench
Artwork
Seating and picnic area
Wayfinding sign
Bench
Bollards
Grass
Steps
Scrub/shrub layer
Grass
Private dwelling
Scrub/shrub layer
Fingerpost
Gate
Steps
Sign
SCALE
0
10m
20m
30m
N
Fingerpost
Scrub/shrub layer
Water Channel
Existing route of steps under aqueduct
1
Scrub/shrub layer
Pontcysyllte Aqueduct
Scrub/shrub layer under tree canopy
Steps
Scrub/shrub layer under tree canopy
Laid hedge
2
Wayfinding post
River Dee

1 Steps close to aqueduct



2 Example of eroded steps

ARCADIS
Glandŵr Cymru
Canal & River Trust in Wales