


Picture number	Room	Description	Photo
0001	Basement Room 1	View of stairs down to basement level	
0002	Basement Room 2	View NW of room with supports for fireplace above	
0003	Basement Room 2	View NE of room with opening through to basement room 4 on right hand side	
0004	Basement Room 2	View SE showing coal chute from King Street	
0005	Basement Room 2	View SW with opening to Basement Room 3	

0006	Basement Room 2	Close up view of coal chute	
0007	Basement Room 3	View of storage bins within Basement Room 3 looking NW	
0008	Basement Room 3	View of storage bins within Basement Room 3 looking W	
0009	Basement Room 3	View of storage bins within Basement Room 3 looking SW	
0010	Basement Room 4	View of room looking NE	

0011	Basement Room 2	Floor finish within Basement Room 2	
0012	Basement Room 2	Replacement floor structure between Basement Room 2 and Ground Floor Room 2	
0013	Basement Room 2	View of doorway between Basement Room 2 and Basement Room 3	
0014	Basement Room 1	View up stairs from Basement Room 1	
0015	Ground Floor Room 1	View NE of room	

0016	Ground Floor Room 1	view NW of room		
0017	Ground Floor Room 1	View SW of room		
0018	Ground Floor Room 1	View S of room showing the internal face of the front door and fanlight		
0019	Ground Floor Room 1	View SE of room		
0020	Ground Floor Room 1	View E of room		





0021	Ground Floor Room 2	View NW of room	
0022	Ground Floor Room 2	View NE of room	
0023	Ground Floor Room 2	View SE of room	
0024	Ground Floor Room 2	View SW of room	
0025	Ground Floor Room 2	Cornice of room looking SE	





0026	Ground Floor Room 2	Cornice of room looking SW	
0027	Ground Floor Room 2	View of window box seat unit	
0028	Ground Floor Room 2	View NW with infill cupboard open	
0029	Ground Floor Room 2	View of window	
0030	Ground Floor Room 2	Detail of architrave and skirting board	




0031	Ground Floor Room 3	View NW of room	
0032	Ground Floor Room 3	View NE of room	
0033	Ground Floor Room 3	View SW of room	
0034	Ground Floor Room 3	View of arched detail moulding and cornice of Ground Floor Room 3	
0035	Ground Floor Room 3	View SE of room	



0036	Ground Floor Room 3	Detail of skirting boards	
0037	Ground Floor Room 3	General view of staircase	
0038	Ground Floor Room 3	detail of staircase, with original scroll details but replacement spindrels	
0039	Ground Floor Room 4	view NW of room	
0040	Ground Floor Room 4	View NE of room	


0041	Ground Floor Room 4	View SE of room	
0042	Ground Floor Room 4	View SW of room	
0043	Ground Floor Room 4	detail of window	
0044	Ground Floor Room 5	view NW of room	
0045	Ground Floor Room 5	View NE of room	




0046	Ground Floor Room 5	Internal face of replacement door	
0047	Ground Floor Room 5	View SE of room	
0048	Ground Floor Room 3	Slate step up from basement	
0049	Ground Floor Room 3	Original door to basement	 
0050	Ground Floor Room 3	Flush external security door to rear	



0051	First Floor Room 1	View NW of room		
0052	First Floor Room 1	View NE of room		
0053	First Floor Room 1	View E of room		
0054	First Floor Room 1	View SW of room		
0055	First Floor Room 1	original paneling remaining in small section of room		

0056	First Floor Room 1	details of original windo moulding and cill.		
0057	First Floor Landing	view doe staircase from half landing		
0058	First Floor Landing	lower section of window separated by staircase		
0059	First Floor Room 2	view NW of room		
0060	First Floor Room 2	View NE of room		



0061	First Floor Room 2	View SE of room	
0062	First Floor Room 2	View SW of room	
0063	First Floor Room 2	detail of window	
0064	First Floor Room 2	Internal face of replacement door	
0065	First Floor Room 3	view NW of room	




0066	First Floor Room 3	View NE of room	
0067	First Floor Room 3	View SE of room	
0068	First Floor Room 3	View SW of room	
0069	First Floor Room 3	detail of skirting boards	
0070	First Floor Room 3	Details of replacement windows with routered glazing bars and horns	 

0071	First Floor Room 3	Cupboard within blocked fireplace	
0072	First Floor Room 4	Storage cupboard with shelving off landing	
0073	First Floor Room 5	View NW of room - glazed screen visible on left hand side	
0074	First Floor Room 5	View NE of room	
0075	First Floor Room 6	view NW of room	


0076	First Floor Room 6	View NE of room	
0077	First Floor Room 6	View SE of room	
0078	First Floor Room 6	View SW of room	
0079	First Floor Room 6	Detail of architrave and window cill	
0080	First Floor Room 7	view NW of room	


0081	First Floor Room 7	View NE of room	
0082	First Floor Room 7	View SE of room	
0083	First Floor Room 7	View SW of room and detail of replacement door	 
0084	First Floor Room 7	Detail of skirting boards	
0085	First Floor Room 7	Detail of architrave and skirting board	

0086	First Floor Room 7	detail of window	
0087	First Floor Room 7	Detail of cornice	
0088	First Floor Landing	View up staircase to second floor	
0089	First Floor Landing	View down staircase to first floor and glazed screen	
0090	First Floor Landing	View down staircase towards First Floor Room 2	

0091	First Floor Landing	Upper section of disected window on the bottom and original clear window above	
0092	First Floor Landing	View up to second floor	
0093	First Floor Landing	detail of disected window	 
0094	Second Floor Room 1	view NW of room	
0095	Second Floor Room 1	View NE of room	

0096	Second Floor Room 1	View SE of room	
0097	Second Floor Room 1	View SW of room	
0098	Second Floor Room 1	detail of cupboard	
0099	Second Floor Room 1	Photo of replacement window	
0100	Second Floor Room 1	Details of replacement windows with routered glazing bars and horns	 


0101	Second Floor Landing	view NW of room	
0102	Second Floor Landing	View NE of room	
0103	Second Floor Landing	View SE of room	
0104	Second Floor Landing	View SW of room	
0105	Second Floor Room 2	view NW of room	

0106	Second Floor Room 2	View NE of room	
0107	Second Floor Room 2	View SE of room	
0108	Second Floor Room 2	View SW of room	
0109	Second Floor Room 2	View of window	
0110	Second Floor Room 2	Detail of window	

0111	Second Floor Room 2	Detail of architrave and window cill	
0112	Second Floor Room 2	Niche for allowing door to open without causing damage - note door knob was approx 50mm lower originally	
0113	Second Floor Room 3	view NW of room	
0114	Second Floor Room 3	View NE of room	
0115	Second Floor Room 3	View SE of room	

0116	Second Floor Room 3	View SW of room	
0117	Second Floor Room 3	View of window	
0118	Second Floor Room 3	Detail of architrave and window cill	
0119	External - Rear	View of rear of property showing outline of the original outrigger	
0120	External - Rear	Adgacent building still retains their outrigger extensions	 

0121	External - Rear	Remains of original outbuildings. Threshold can be seen	
0122	External - Rear	Vertical line in brickwork suggesting original location of door between the property and the outrigger	
0123	External - Rear	View towards East and Rhosddu Road	
0124	External - Rear	View from Rhosddu Road	
0125	External - Rear	Detail of original boundary treatment	

0126	External - Rear	Detail of floor covering			
0127	External - Rear	View SE between the property and No 63			
0128	External - Rear	External view of window to First Floor Room 1 with original glass			
0129	External - Rear	View SE between the property and No 63 showing overhang of eaves			
0130	External - King Street	view of property from King Street			

0131	External - King Street	view of chimney stack with replacement pots.	
0132	External - King Street	Detail of original dressed stone ridge tiles	
0133	External - King Street	Detail of upper floor brickwork	
0134	External - King Street	Wider view from King Street	
0135	External - King Street	Detail of fanlight over main door	

0136	External - King Street	Detail of plaque embelishments that adorne the terrace	
0137	External - King Street	photo of main entrance door and fanlight	
0138	External - King Street	View from Rhosddu Road	
0139	External - King Street	Oblique view from King Street	