ST DAVIDS CHURCH, RHOSLLANERCHRUGOG – RECORD PHOTOGRAPHS OF DISTRESS



MASONRY FRACTURES AT ARCH CROWN EAST END OF NAVE /NORTH AISLE AND NAVE OPENING TO CHANCEL



MASONRY FRACTURE AT EAST END OF NAVE – OPENING TO NORTH AISLE



MASONRY FRACTURE – CROWN OF ARCHED OPENING FROM NAVE TO CHANCEL