ST DAVIDS CHURCH, RHOSLLANERCHRUGOG – RECORD PHOTOGRAPHS OF DISTRESS





MASONRY FRACTURE OVER ENTRANCE DOORWAY



MASONRY FRACTURE IN ARCHED OPENING BETWEEN NAVE AND NORTH AISLE



CRACKING IN NORTH AISLE END WALL – DUE TO FOUNDATION SETTLEMENT