




SOAKAWAY ASSESSMENT

Project Number: PT1346	Site Address: Land Off St Mary's Avenue, Wrexham, LL13 0EQ	
Weather: Heavy Rain	Date Of Testing: 21/11/2022	Client:

Site Location GPS



Site Photo





RESULTS

Percolation Tests In Line With BRE365

Trial Pit:	Length:	Width:	Depth:	Depth of water (at 100%)
A (4)	1000	300	2000	1000

Notes:
Ground Water encroached during excavation, trail pit left open for remaining time on site - 1.7m bgl

Ground Water Encroached During Excavation	Depth Of Ground Water
Yes	1.7m BGL

RESULTS

Percolation Tests In Line With BRE365

Trial Pit:	Length:	Width:	Depth:	Depth of water (at 100%)
B (5)	1000	300	2000	1000


Notes:
Ground Water encroached during excavation, trail pit left open for remaining time on site - 1.5m bgl

Ground Water Encroached During Excavation	Depth Of Ground Water
Yes	1.5m BGL



SITE PLAN

Site Layout





PERCOLATIONTESTS.CO.UK

PHOTOS

Trial Pit A



Trial Pit B

