

APPENDIX A – SITE PHOTOGRAPHS



Photo 1 – Southern side of the site facing west



Photo 2 – Northern side of the site facing northwest



Photo 3 - Northern side of the site facing east



Photo 4 – Central area of the site



Photo 5 – Old container with evidence of fly tipping inside located at the south of the site.