



2nd Excavation adjacent to main entrance gateway – access point on rising main





Access point repaired on rising main 2nd excavation & back filled





Access point excavated on rising main 3rd excavation in hedge line





Access point repaired on 3rd excavation & back filled





Generic No MH08 in footpath opposite Wrexham University & CCTV showing from rising main



Generic No MH09 in Garden of No3 Lilac Road – Cover seized



Generic No MH10 in footpath outside No 9 Lilac Road





Generic No MH11 in footpath to gable end of No 16 Lilac Road





Generic No MH12 in grass verge to gable end of No 26 Lilac Road





Generic No MH13 in footpath to rear of No 14 Plas y Ffynnon





Generic No MH14 in footpath to front of No 17 Plas y Ffynnon





Generic No MH15 in grass area to rear of No 15 Plas y Ffynnon





Generic No MH15 discharging to outfall at watercourse

