

Supporting Document Summary

Pre-existing	No change to file or details
Revised	No change to file, details updated
New	New file added to this version
Deleted	File removed from this version

Proposal Name	Ash tree
Reference	PP-12214021
Version Number	1
Submission Date	06/06/2023
Attachments	
Document Name	Evidence to verify application
Document Description	Crack in wall
Status	New
Submission Date	05/06/2023
Submission Method	Uploaded to storage
File Name	20230605_160609.jpg
File Type	image/jpeg
File Size (bytes)	3863173

Document Name	Evidence to verify application
Document Description	Crack in wall
Status	New
Submission Date	05/06/2023
Submission Method	Uploaded to storage
File Name	20230605_160646.jpg
File Type	image/jpeg
File Size (bytes)	4540436
Document Name	Evidence to verify application
Document Description	Crack in wall
Status	New
Submission Date	05/06/2023
Submission Method	Uploaded to storage
File Name	20230605_160613.jpg
File Type	image/jpeg
File Size (bytes)	4494429

Document Name	Evidence to verify application
Document Description	Crack in wall
Status	New
Submission Date	05/06/2023
Submission Method	Uploaded to storage
File Name	20230605_160649.jpg
File Type	image/jpeg
File Size (bytes)	3377187
Document Name	The location plan
Document Description	Ash tree location
Status	New
Submission Date	05/06/2023
Submission Method	Uploaded to storage
File Name	Screenshot_20230605_162145_Maps.jpg
File Type	image/jpeg
File Size (bytes)	279816

Document Name	Additional plans
Document Description	Plans of property
Status	New
Submission Date	06/06/2023
Submission Method	Uploaded to storage
File Name	TQRQM23157154556015.pdf
File Type	application/pdf
File Size (bytes)	308422