


View From Well Street.

Front Elevation showing existing ground floor window and first floor arched windows proposed for replacement



Ms Barker
Chapel House Well Street, LL14 3AN

Existing Windows: Photosheets
ref: CH02

Planning Ref: PP-11724574

View From Well Street.

East elevation showing ground floor and first floor window to be replaced.



Ms Barker
Chapel House Well Street, LL14 3AN

Existing Windows: Photosheets
ref: CH02

Planning Ref: PP-11724574

View From Bin Store Area

East elevation showing ground floor and first floor window to be replaced.



Ms Barker
Chapel House Well Street, LL14 3AN

Existing Windows: Photosheets
ref: CH02

Planning Ref: PP-11724574

East elevation interior view of ground floor window.



Ms Barker
Chapel House Well Street, LL14 3AN

Existing Windows: Photosheets
ref: CH02


Planning Ref: PP-11724574

East elevation interior view of first floor window.



View From Well Street.

West elevation showing ground floor and first floor window to be replaced. West elevation in the rear distance shows ground floor window to be replaced.



Ms Barker
Chapel House Well Street, LL14 3AN

Existing Windows: Photosheets
ref: CH02

Planning Ref: PP-11724574

View From Neighbouring Bin Store Area

West elevation showing ground floor and first floor window to be replaced.



Ms Barker
Chapel House Well Street, LL14 3AN

Existing Windows: Photosheets
ref: CH02

Planning Ref: PP-11724574

West elevation interior view of ground floor window.



Ms Barker
Chapel House Well Street, LL14 3AN

Existing Windows: Photosheets
ref: CH02

Planning Ref: PP-11724574

West elevation interior view of rear ground floor window.



Ms Barker
Chapel House Well Street, LL14 3AN

Existing Windows: Photosheets
ref: CH02

Planning Ref: PP-11724574

West elevation interior view of first floor window.

