

Brunett and blossom barns photograph thumbnail descriptions.



Photograph showing bat nesting boxes situated in the oak tree as outlined in the ecological survey.



Photograph showing additional nesting box fixed to the gable end of main barn building



photograph showing additional nesting box fixed to the stable gable



photograph showing ridge tiles raised to allow bat access as per ecological survey.