

Estimate Summary



Site Type	STORES	Store Name	Wrexham Extra
Store Number	3433	Supplier Name	Ground Control
Version No	V.9.2	Location	SITE
Area	EXTERNAL	Sub-Element	SHRUBS, BUSHES, TREES
Element	SOFT LANDSCAPING	Who requested it?	Stanley Fairchild
Works Order No	74234302		
		% of area to be replaced/repared	

Describe the works required	section fell 3 number Alders growing into the building and also blocking CCTV
-----------------------------	---

Why do we need to do it? (e.g. mandatory or statutory, beyond economical repair)	prevents camera from being able to see the backgate and in the event of a fire could risk the integrity of the building
--	---

How will you do it? (e.g. How will you programme works to mitigate risks)	Our certified team shall attend site and section fell 3 Alders
---	--

What are the risks? (describe any risks e.g. trade, h&s, people)	Public/Staff/Tesco Staff/Property damage
--	--

