
Intended for
Kronospan Ltd

Document type
Report

Date
October 2021

KRONOSPAN RAW BOARD STORE PRELIMINARY RISK ASSESSMENT AND CONTAMINATED LAND INTERPRETIVE REPORT

KRONOSPAN RAW BOARD STORE PRELIMINARY RISK ASSESSMENT AND CONTAMINATED LAND INTERPRETIVE REPORT

Project name	Raw Board Store
Project no.	1620010941
Recipient	Kronospan Ltd
Document type	Report
Document number	1620010941-RAM-EGT-00-RP-EN-0001
Version	P04
Date	22/10/2021
Prepared by	Damian Watkin / Viktoriya Grygoryshchak
Checked by	Peter Fitch
Approved by	John Whitfield
Description	Preliminary Risk Assessment and Contaminated Land Interpretative Report

Ramboll
2nd Floor, The Exchange
St John Street
Chester
CH1 1DA
United Kingdom

T +44 1244 311855
<https://uk.ramboll.com>

This report is produced by Ramboll at the request of the client for the purposes detailed herein. This report and accompanying documents are intended solely for the use and benefit of the client for this purpose only and may not be used by or disclosed to, in whole or in part, any other person without the express written consent of Ramboll. Ramboll neither owes nor accepts any duty to any third party and shall not be liable for any loss, damage or expense of whatsoever nature which is caused by their reliance on the information contained in this report.

Ramboll UK Limited
Registered in England & Wales
Company No: 03659970
Registered office:
240 Blackfriars Road
London
SE1 8NW

CONTENTS

1.	INTRODUCTION	3
1.1	Existing Information	3
1.2	Planning Permission	3
1.3	Objectives	4
1.4	Reporting	5
1.5	Constraints and Limitations	5
2.	SITE SETTING	7
2.1	Site Location and Description	7
2.2	Development Proposal	7
3.	PREVIOUS REPORTS	10
4.	HISTORICAL & REGULATORY INFORMATION	12
4.1	Map History	12
4.2	Environmental Database Records	13
4.3	Potential for Ground Contamination	15
5.	ENVIRONMENTAL SETTING	16
5.1	Geology and hydrogeology	16
5.2	Coal Mining	17
5.3	Hydrology	17
5.4	Ecology	18
6.	PRELIMINARY RISK ASSESSMENT	19
6.1	Potential Sources	20
6.2	Potential Receptors	20
6.3	Potential Pathways	21
6.4	Qualitative Risk Assessment	23
6.5	Summary of Preliminary Risk Assessment	25
7.	GROUND INVESTIGATION	26
7.1	Design	26
7.2	Ground Investigation Activities	26
7.3	Laboratory Analysis – Contamination	27
7.4	Groundwater and Ground Gas Monitoring	28
8.	GROUND CONDITIONS	30
8.1	Ground Conditions Encountered	30
8.2	Groundwater	31
8.3	Visual and Olfactory Observations of Potential Contamination	33
9.	GROUND CONTAMINATION – GENERIC QUANTITATIVE RISK ASSESSMENTS	34
9.1	Introduction	34
9.2	Human Health Assessment	34
9.3	Groundwater Contamination	35
10.	GROUND GAS RISK ASSESSMENT	39
10.1	Methodology	39
10.2	Ground Gas During Site Works	39
10.3	Ground Gas Monitoring Data	39
10.4	Volatile Vapours	42
11.	GROUNDWATER DQRA	45
11.1	Introduction	45
11.2	DQRA Results	46
12.	SOIL WASTE CLASSIFICATION	47
12.1	Methodology	47

13.	CONTAMINATED LAND RISK ASSESSMENT	48
13.1	Conceptual Site Model	48
13.2	Qualitative Risk Assessment	49
14.	CONCLUSIONS AND RECOMMENDATIONS	52

APPENDICES

Appendix 1

Landmark Envirocheck Report

Appendix 2

Geotechnics (2020) Ground Investigation Factual Report

Appendix 3

Groundwater DQRA