

Cerys Jones

From: Mark Walters <mark.walters@cpat.org.uk>
Sent: 10 October 2018 16:29
To: planning; Kevin Hughes
Subject: P/2018/0834 33 - 35 Brook Street, Wrexham

Dear Kevin

With regard to the photographic survey received so far we recently rejected the photos as they do not meet the requirements of the condition. A very small number of external images only were received which were are very poor quality. The condition required archaeological contractors to complete this survey, not the applicant or their agent. We understand that there may be some access issues to photograph internally and that access may only be granted with Health and Safety Executive permission and HSE staff on-site. The latter option should be investigated prior to demolition of this building.

Kind regards

Mark Walters

Mark Walters
Development Control Archaeologist / Swyddog Rheoli Datblygiad

Ffôn / Tel: 01938 553670/552035 Mobile: 07736 163148

E-bost / E-mail: mark.walters@cpat.org.uk

Ymddiriedolaeth Archaeolegol Clwyd-Powys, 41 Stryd Lydan, Y Trallwng, SY21 7RR Swyddfa Gofrestredig fel yr uchod. Rhif Cwmni 1212455, Rhif Elusen 508301, Sefydliad Cofrestredig IfA, Rhif 6.

Clwyd-Powys Archaeological Trust, 41 Broad Street, Welshpool, SY21 7RR Registered Office as above. Company No 1212455, Charity No 508301. Chartered Institute for Archaeologists Registered Organisation No 6.

Please note that I do not work Fridays

[Privacy Notice](#)