

# *GroundSolve Ltd*

*Consulting Geotechnical, Engineering Geology and Environmental Engineers.*

Unit 1 Charter Court,  
Well House Barns,  
Chester Road, Bretton,  
Flintshire, CH4 0DH


Tel: 01244 661361

Mob: 07977 218184

Email: [mikescott@groundsolve.com](mailto:mikescott@groundsolve.com)

REF: 1778/TF/AGReply02/mjs

Angela Guy  
Public Protection Service  
Wrexham County Borough Council  
Ruthin Road  
Wrexham LL13 7TU



15<sup>th</sup> July 2016

Dear Angela,

**RE: TOTAL FITNESS, STANSTY ROAD, WREXHAM**


Thank you for your e-mail of the 30<sup>th</sup> June 2016, in reply to your queries we have the following response.

We have checked with Mike Forgrave of Gower Homes and the site boundary is at the top of the embankment, apparently there is a fence line, which is obscured by the vegetation. The actual slope belongs to the railways.

With regard to the testing it is our experience that the TPHCWG and PAH speciation is sufficient to enable any fuel spills to be identified and we are happy we have sufficient testing scheduled.

We trust this is satisfactory, should you have any queries please call Mike Scott on 01244 661361.

Yours sincerely

  
M J Scott  
Enc.

CC Mike Forgrave Gower Homes