

Matthew Phillips

From: Josh Braithwaite <josh@braithwaitegroup.com>
Sent: 17 June 2021 19:54
To: Chris Smith
Cc: ILONA MAZUREK; Christian Fernandez-Hughes
Subject: Gas Membrane
Attachments: Gas Membrane Installation 01[1].jpg; Gas Membrane Installation 02.jpg

Follow Up Flag: Follow up
Flag Status: Flagged

Hi Chris,

See comments and pictures.

Gas Membrane Repair Process

Certain areas within the shop floor had a number of drainage popups that required Civils & Construction operatives to cut into the gas membrane which would allow the membrane to sit over the drainage pipe. These areas were then sleeved with an additional 2000 gauge membrane cut out and taped with radon barrier tape with laps as per the specification required.

Josh Braithwaite // Managing Director

m 077 385 79 555

e josh@braithwaitegroup.com

t (0044) 151 236 3203

braithwaitegroup.com



Confidentiality Notice and Legal Liability Waiver: The information contained in this e-mail message and any attachment is for the intended recipients only. It may contain confidential, privileged or copyright material. If you receive this e-mail in error please delete it and any attachments and notify the sender immediately by reply e-mail. Any use, reading, copying, distributing or disclosure of the information in this e-mail is strictly prohibited if you are not the intended recipient. Any views expressed in this e-mail are not necessarily those of Braithwaite Fit Out Ltd. Braithwaite Fit Out Ltd does not warrant that this e-mail is free from viruses or other defects, Braithwaite Fit Out is not liable for any loss, damage or other consequences that may arise from opening or using this e-mail and any attachments.