



Reproduced from Ordnance Survey Mapping with the permission of the Controller of HMSO
© Crown Copyright SHEPHERD GILMOUR ENVIRONMENT LTD License No AL52385A0001

©Crown Copyright SHEPHERD GILMOUR ENVIRONMENT LTD License No. AL52385A0001



SHEPHERD • GILMOUR

Environment Limited

Castlefield House, 29, Ellesmere Street, Manchester. M15 4LZ.

**Land Off Bryn Lane (Plot 3A), Wrexham
Industrial Estate**

[illegible]

Site Location Plan

DRAWING NO.

ME1178/01

SCALE


N/A

DRAWN BY

CM

DATE _____


06/10/11



- LEGENDA**
- "Os Cardeais" (Bis-dominados de São)
 - Sede do Arcebispo (São Paulo)
 - Arcebispo Domestico (Presidente do Tribunal)
 - Bispo do Estado (Presidente)
 - prelado "auxiliar"
 - grande-arcebispo
 - arcebispo coadjutor
 - prelado "auxiliar" do Bispo
 - prelado "auxiliar" do Bispo
 - prelado "auxiliar" do Bispo

APPENDIX C

Environmental Database Search Information



EmapSite
Masdar House,
Eversley, RG27 0RP

Report Reference:	EMS- 139229_199276
Your Reference:	EMS_139229_199 276
Report Date	Sep 27, 2011
Report Delivery Method:	Email - pdf

GroundSure GeoInsight

Address: wrexham

Dear Sir/Madam,

Thank you for placing your order with GroundSure. Please find enclosed the **GroundSure GeoInsight** as requested.

If you would like further assistance regarding this report then please contact the emapsite customer services team on 0118 9736883 quoting the above report reference number.

Yours faithfully,

emapsite customer services team

Enc.
GroundSure GeoInsight


GroundSure GeoInsight

Address: wrexham

Date: Sep 27, 2011

Report Reference: EMS-139229_199276

Your Reference: EMS_139229_199276



Brought to you by emapsite

Aerial Photograph of Study Site



Site Name: wrexham
Grid Reference: 339232,350747
Size of Site: 21.66 ha

Aerial photography supplied by Getmapping PLC.
© Copyright Getmapping PLC 2003. All Rights Reserved.

Overview of Findings

The GroundSure GeoInsight provides high quality geo-environmental information that allows geo-environmental professionals and their clients to make informed decisions and be forewarned of potential ground instability problems that may affect the ground investigation, foundation design and possibly remediation options that could lead to possible additional costs.

The report is based on the BGS 1:50,000 Digital Geological Map of Great Britain, BGS Geosure data; BRITPITS database; Shallow Mining data and Borehole Records, Coal Authority data including brine extraction areas, PBA non-coal mining and natural cavities database, Johnson Poole and Bloomer mining data and GroundSure's unique database including historical surface ground and underground workings.

For further details on each dataset, please refer to each individual section in the report as listed. Where the database has been searched a numerical result will be recorded. Where the database has not been searched '-' will be recorded.

Report Section	Number of records found within (X) m of the study site boundary
1. Geology	Description
1.1 Artificial Ground,	
1.1.1 Is there any Artificial Ground /Made Ground present beneath the study site?*	No
1.1.2 Are there any records relating to permeability of artificial ground within the study site* boundary?	No
1.2 Superficial Geology & Landslips	
1.2.1 Is there any Superficial Ground/Drift Geology present beneath the study site?*	Yes
1.2.2 Are there any records relating to permeability of superficial geology within the study site* boundary?	Yes
1.2.3 Are there any records of landslip within 500m of the study site boundary?	No
1.2.4 Are there any records relating to permeability of landslips within the study site* boundary?	No
1.3 Bedrock, Solid Geology & Faults	
1.3.1 For records of Bedrock and Solid Geology beneath the study site* see the detailed findings section.	
1.3.2 Are there any records relating to permeability of bedrock within the study site* boundary?	Yes
1.3.3 Are there any records of faults within 500m of the study site boundary?	Yes
1.3.4 Is the property in a Radon Affected Area as defined by the Health Protection Agency (HPA) and if so what percentage of homes are above the Action Level?	The property is not in a Radon Affected Area, as less than 1% of properties are above the Action Level
1.3.5 Is the property in an area where Radon Protection Measures are required for new properties or extensions to existing ones as described in publication BR211 by the Building Research Establishment?	No radon protective measures are necessary

* This includes an automatically generated 50m buffer zone around the site

Source:Scale 1:50,000 BGS Sheet No:122

2. Ground Workings	on-site	0-50	51-250	251-500	501-1000
2.1 Historical Surface Ground Working Features from Small Scale Mapping	13	1	42	-	-
2.2 Historical Underground Workings Features from Small Scale Mapping	0	0	0	0	0
2.3 Current Ground Workings	0	0	0	0	0

3. Mining, Extraction & Natural Cavities	on-site	0-50	51-250	251-500	501-1000
3.1 Historical Mining	0	0	0	0	0
3.2 Coal Mining	1	0	0	0	0
3.3 Johnson Poole and Bloomer Mining Area	0	0	0	0	0
3.4 Non-Coal Mining*	0	0	0	0	0
3.5 Non-Coal Mining Cavities	0	0	0	0	0
3.6 Natural Cavities	0	0	0	0	0
3.7 Brine Extraction	0	0	0	0	0
3.8 Gypsum Extraction	0	0	0	0	0
3.9 Tin Mining	0	0	0	0	0
3.10 Clay Mining	0	0	0	0	0

*This includes an automatically generated 50m buffer zone around the site


4. Natural Ground Subsidence	on-site*	0-50	51-250	251-500	501-1000
4.1 Shrink-Swell Clay	Very Low	-	-	-	-
4.2 Landslides	Very Low	-	-	-	-
4.3 Ground Dissolution of Soluble Rocks	Negligible	-	-	-	-
4.4 Compressible Deposits	Negligible	-	-	-	-
4.5 Collapsible Deposits	Very Low	-	-	-	-
4.6 Running Sand	Very Low	-	-	-	-

* This includes an automatically generated 50m buffer zone around the site

5. Borehole Records	on-site	0-50	51-250	251-500	501-1000
5.1 BGS Recorded Boreholes	1	2	16	-	-

6. Estimated Background Soil Chemistry	on-site	0-50	51-250	251-500	501-1000
6.1 Records of Background Soil Chemistry	4	0	0	-	-


1.1 Artificial Ground Map



Artificial Ground Legend



Crown Copyright. All Rights Reserved
Licence Number: 100035207



Geological information represented on the mapping is derived from the BGS Digital Geological map of Great Britain at 1:50,000 scale.

1.1 Artificial Ground

The following geological information represented on the mapping is derived from 1:50,000 scale BGS Geological mapping, Sheet No:122

1.1.1 Artificial/Made Ground

Are there any records of Artificial/Made Ground within 500m of the study site boundary? **Yes**

ID	Distance (m)	Direction	LEX Code	Description	Rock Description
1	376.0	W	LSGR-UNKN	LANDSCAPED GROUND (UNDIVIDED)	UNKNOWN/UNCLASSIFIED ENTRY


1.1.2 Permeability of Artificial Ground

Are there any records relating to permeability of artificial ground within the study site* boundary? **No**

Database searched and no data found.

* This includes an automatically generated 50m buffer zone around the site.

1.2 Superficial Deposits and Landslips Map




Superficial and Landslips Legend



Crown Copyright. All Rights Reserved
Licence Number: 100035207



Site Outline



Search Buffers (m)

Geological information represented on the mapping is derived from the BGS Digital Geological map of Great Britain at 1:50,000 scale.

1.2 Superficial Deposits and Landslips

1.2.1 Superficial Deposits/Drift Geology

Are there any records of Superficial Deposits/Drift Geology within 500m of the study site boundary? **Yes**

ID	Distance (m)	Direction	Lex Code	Description	Rock Description
1	0.0	On Site	TILLD-DMTN	TILL, DEVENSIAN	DIAMICTON
2	376.0	W	TILLD-DMTN	TILL, DEVENSIAN	DIAMICTON

1.2.2 Permeability of Superficial Ground

Are there any records relating to permeability of superficial ground within the study site* boundary? **Yes**

Distance (m)	Direction	Flow type	Maximum Permeability	Minimum Permeability
0.0	On Site	Mixed	High	Low

1.2.3 Landslip

Are there any records of Landslip within 500m of the study site boundary?

No

Database searched and no data found.

The geology map for the site and surrounding area are extracted from the BGS Digital Geological Map of Great Britain at 1:50,000 scale.

This Geology shows the main components as discrete layers, these are: Artificial / Made Ground, Superficial / Drift Geology and Landslips. These are all displayed with the BGS Lexicon code for the rock unit and BGS sheet number. Not all of the main geological components have nationwide coverage.

1.2.4 Landslip Permeability


Are there any records relating to permeability of landslips within the study site* boundary?

No

Database searched and no data found.

*This includes an automatically generated 50m buffer zone around the site.

1.3 Bedrock and Faults Map




Bedrock & Faults Deposits Legend



Crown Copyright. All Rights Reserved
Licence Number: 100035207



Site Outline



Search Buffers (m)

Geological information represented on the mapping is derived from the BGS Digital Geological map of Great Britain at 1:50,000 scale.

1.3 Bedrock, Solid Geology & Faults

The following geological information represented on the mapping is derived from 1:50,000 scale BGS Geological mapping, Sheet No:122

1.3.1 Bedrock/Solid Geology

Records of Bedrock/Solid Geology within 500m of the study site boundary:

ID	Distance (m)	Direction	LEX Code	Rock Description	Rock Age
1	0.0	On Site	SAL-MDSC	Salop Formation - Mudstone, Sandstone And Conglomerate	/ Westphalian D
2	0.0	On Site	KNSF-SDST	Kinnerton Sandstone Formation - Sandstone	Scythian
3	376.0	W	SAL-MDSC	Salop Formation - Mudstone, Sandstone And Conglomerate	/ Westphalian D
4	416.0	NW	KNSF-SDST	Kinnerton Sandstone Formation - Sandstone	Scythian
5	426.0	N	KNSF-SDST	Kinnerton Sandstone Formation - Sandstone	Scythian
6	440.0	NW	KNSF-SDST	Kinnerton Sandstone Formation - Sandstone	Scythian

1.3.2 Permeability of Bedrock Ground

Are there any records relating to permeability of bedrock ground within the study site* boundary? **Yes**

Distance (m)	Direction	Flow type	Maximum Permeability	Minimum Permeability
0.0	On Site	Fracture	Moderate	Low
0.0	On Site	Intergranular	High	High

1.3.3 Faults

Are there any records of Faults within 500m of the study site boundary? **Yes**

ID	Distance (m)	Direction	Category Description	Feature Description
8	416.0	NW	FAULT	Normal fault, inferred
9	426.0	N	FAULT	Normal fault, inferred
10	440.0	NW	FAULT	Normal fault, inferred

The geology map for the site and surrounding area are extracted from the BGS Digital Geological Map of Great Britain at 1:50,000 scale.

This Geology shows the main components as discrete layers, these are: Bedrock/ Solid Geology and linear features such as Faults. These are all displayed with the BGS Lexicon code for the rock unit and BGS sheet number. Not all of the main geological components have nationwide coverage.

1.3.4 Radon Affected Areas

Is the property in a Radon Affected Area as defined by the Health Protection Agency (HPA) and if so what percentage of homes are above the Action Level?

The property is not in a Radon Affected Area, as less than 1% of properties are above the Action Level


* This includes an automatically generated 50m buffer zone around the site.

1.3.5 Radon Protection

Is the property in an area where Radon Protection are required for new properties or extensions to existing ones as described in publication BR211 by the Building Research Establishment?

No radon protective measures are necessary

2. Ground Workings Map



Ground Workings Legend



Crown Copyright. All Rights Reserved
Licence Number: 100035207

- | | | | |
|--|--------------------|--|----------------------------------|
| | Site Outline | | Historic Surface Ground Workings |
| | Search Buffers (m) | | Historic Underground Workings |
| | | | Current Ground Workings |