

Planning Appeal: Fencing erected at Blythswood, 112 Norman Road, Wrexham, LL13LBE

Supporting Photographs 8



Above photograph shows existing fencing that extends to ground level and the top of the retaining wall at hip level, which would still represent a fall hazard if not adequately protected. The photograph also shows extant metal brackets from a previous fencing structure (style unknown).