


VISIBILITY ENTRANCE DRIVE IMPROVEMENTS
RHECROFT MEADOWS EXERCISE FIELD
OLD WREXHAM ROAD, GRESFORD
EXISTING PLAN



Existing hedgerow
& trees outside the
visibility splay area
apart from minor
infringement into
zone to north corner
of field.

Central hedge
and verge

Access drive to
Caia Farmhouse

APPLICATION SITE ENTRANCE
ACCESS DRIVE

Existing
ash tree

Existing mature
sycamore

Hedge and
low bank

Red hatched area
within required
visibility splays

Drawing number: PJH/24/2021/GRES/02

Scale - 1:200 @ A3