

APPENDIX A

Site Photographs



Photograph 1 Previous Bungalow on site



Photograph 2 Rear of Bungalow



Photograph 3 looking north post demolition



Photograph 4 Western site boundary



Photograph 5 looking south



Photograph 6 Site entrance



Photograph 7 Site entrance and Bryn Glas from the south



Photograph 8 Site entrance looking west



Photograph 9 looking south west



Photograph 10 Felled trees



Photograph 11 looking north



Photograph 12 north east corner of site at plotted shaft location