



View East: Gully leading from concrete service cover. Drainage pipe exposed in northern gully face



Drainage pipe in eastern face of concrete service cover

Notes:	Project	Wrexham SI	Plate 3
	Project No.	F9042-19	
	Carried out for	Conrad Energy	



View North from concrete service cover towards northern site boundary



View North at eastern end of site – mature trees on boundary

Notes:	Project	Wrexham SI	Plate 4
	Project No.	F9042-19	
	Carried out for	Conrad Energy	



View North West of spoil heap created during site clearance



View South along eastern site boundary

Notes:	Project	Wrexham SI	Plate 5
	Project No.	F9042-19	
	Carried out for	Conrad Energy	



View South showing path of OHL



View East along southern site of gully showing southern site boundary

Notes:	Project	Wrexham SI	Plate 6
	Project No.	F9042-19	
	Carried out for	Conrad Energy	



South East corner of site



View West along southern site boundary

Notes:	Project	Wrexham SI	Plate 7
	Project No.	F9042-19	
	Carried out for	Conrad Energy	