

63 King Street, Wrexham

Existing Features-Photographic Schedule



Lawray Architects
The Byre
Croesnewydd Hall
Wrexham
LL13 7YP

June 2017



Fig 1-Hallway to entrance door




Fig 2-Hallway from Entrance



Fig 3-Ground Floor Office/Hallway
door



Fig 4-First to Second Floor Stair String




Fig 5-Second Floor Landing



Fig 6-First to Second Floor Stair Flight



Fig 7-First Floor Front Office



Fig 8-First Floor Rear Office doorway to Landing



Fig 9-Second Floor Office Cupboard

Commentary

Fig 1: Hallway to Entrance Door;

Existing external door retained, coving and skirting remain. Floor finish under over-boarding to be exposed.

Fig 2: Hallway from Entrance;

Door surrounds, coving and skirtings retained.

Fig 3: Ground Floor Office/Hallway Door;

Covings, door surround, skirting and recess retained.

Fig 4: First to Second Floor Stair String;

Flight to remain intact (Flight from Ground to First Floor previously replaced).

Fig 5: Second Floor Landing;

Flight and Balustrading to remain intact.

Fig 6: First to Second Floor Stair Flight;

Flight to remain intact.

Fig 7: First Floor Front Office;

Coving, picture rail, window surround and skirting retained. Original floor boarding to be exposed.

Fig 8: First Floor Rear Office;

Door surround and skirting retained. Original floor boarding to be exposed.

Fig 9: Second Floor Rear Office;

Door surround and skirting retained. Cupboard door retained for re-use.