

24th January 2019

Land South of 14
Tabor Hill
Coedpoeth
Wrexham
LL11 3RU

Re: Test Report 18/18460 Batch 1 – Tabor Hill, Coedpoeth

WAC Test Statement on Spoil State

This test was carried out from spoil on site. In reviewing values these are below trigger levels.

Please see attached - Test Report 18/18460 Batch 1.

Yours sincerely,



P Russell