



 Earth Environmental & Geotechnical Ltd Houldsworth Mill Business & Arts Centre Houldsworth Street Stockport SK5 6DA				PROBEHOLE LOG				Probehole No. WS1	
Project Name: ALDI, Plas Coch Road Location: Wrexham Client: SWF Consulting Ltd				Project No. A2217 Coordinates: 332614E 351469N Level:		Date: 30/08/2017 Logged By: NR Approved By:		Scale: Hole Type: WS	
Well	Water Strikes	Sample Depth (m)	Sample Type	Test Results	Hand Penetrometer Cu (kN/m²)	Depth (m)	Legend	Stratum Description	
		0.20	ENV	SPT 1.00-1.45 1/1/2/2/2/2 N=8		0.15		Asphalt	
		0.70	ENV			0.30		Loose dark grey slightly silty, sandy angular to subangular, fine to coarse GRAVEL of limestone. Sand is fine to coarse.	
						2.10		Firm brown silty, sandy slightly gravelly CLAY. Gravel is angular to subrounded, fine to coarse of sandstone and limestone. Sand is fine to coarse. Occasional lenses of fine to coarse sand.	
				SPT 2.00-2.45 1/1/3/2/2/2 N=9				Loose becoming medium dense brown slightly clayey, slightly silty, sandy angular to subrounded, fine to coarse GRAVEL of sandstone. Sand is fine to coarse with occasional fragments of coal.	2
				SPT 3.00-3.45 2/2/3/5/6/6 N=20		3.00			3
Remarks 1. Hole location scanned with CAT. 2. Backfilled with arisings. 3.									4

PROBEHOLE LOG

Probehole No.

WS2

Project Name: ALDI, Plas Coch Road

Location: Wrexham

Client: SWF Consulting Ltd

Project No. A2217

Coordinates: 332646E 351443N

Level:


Date: 30/08/2017

Logged By: NR

Approved By:



Scale:

Hole Type: WS

Well	Water Strikes	Sample Depth (m)	Sample Type	Test Results	Hand Penetrometer Cu (kN/m²)	Depth (m)	Legend	Stratum Description	
		0.50	ENV	SPT 1.00-1.45 1/2/2/2/3/2 N=9		0.08		Asphalt	1
								Loose dark grey slightly silty, sandy angular to subangular, fine to coarse GRAVEL of limestone. Sand is fine to coarse.	
		1.00	ENV			0.60		Stiff brown silty, sandy slightly gravelly CLAY. Gravel is angular to subrounded, fine to coarse of sandstone and limestone. Sand is fine to coarse. Occasional lenses of fine to coarse sand.	2
		2.0	ENV	SPT 2.00-2.45 2/2/2/2/2/2 N=8		1.50		Loose becoming medium dense brown slightly clayey, slightly silty, sandy angular to subrounded, fine to coarse GRAVEL of sandstone. Sand is fine to coarse with occasional fragments of coal.	
				SPT 3.00-3.45 2/2/4/4/6/5 N=19		3.00			

Remarks

1. Hole location scanned with CAT.
2. Backfilled with arisings.
- 3.

 Earth Environmental & Geotechnical Ltd Houldsworth Mill Business & Arts Centre Houldsworth Street Stockport SK5 6DA				PROBEHOLE LOG				Probehole No. WS3	
Project Name: ALDI, Plas Coch Road Location: Wrexham Client: SWF Consulting Ltd				Project No. A2217 Coordinates: 332657E 351443N Level:		Date: 30/08/2017 Logged By: NR Approved By:		Scale: Hole Type: WS	
Well	Water Strikes	Sample Depth (m)	Sample Type	Test Results	Hand Penetrometer Cu (kN/m²)	Depth (m)	Legend	Stratum Description	
		0.50	ENV	SPT 1.00-1.45 1/1/3/4/3/3 N=13		0.11		Asphalt	1
								Loose dark grey slightly silty, sandy angular to subangular, fine to coarse GRAVEL of limestone. Sand is fine to coarse.	
		1.50	ENV	SPT 2.00-2.45 2/3/3/4/3/4 N=14		0.80		Stiff brown silty, sandy slightly gravelly CLAY. Gravel is angular to subrounded, fine to coarse of sandstone and limestone. Sand is fine to coarse. Occasional lenses of fine to coarse sand.	2
		1.90				Medium dense brown slightly clayey, slightly silty, sandy angular to subrounded, fine to coarse GRAVEL of sandstone. Sand is fine to coarse with occasional fragments of coal.			
				SPT 3.00-3.45 2/3/3/4/5/6 N=18		3.00			3
Remarks 1. Hole location scanned with CAT. 2. Backfilled with arisings. 3.									4

PROBEHOLE LOG

Probehole No.

WS4

Project Name: ALDI, Plas Coch Road

Location: Wrexham

Client: SWF Consulting Ltd

Project No. A2217

Coordinates: 332663E 351443N

Level:



Date: 30/08/2017

Logged By: NR

Approved By:

Scale:

Hole Type: WS

Well	Water Strikes	Sample Depth (m)	Sample Type	Test Results	Hand Penetrometer Cu (kN/m²)	Depth (m)	Legend	Stratum Description		
		0.50	ENV			0.07		Asphalt	1	
										Loose becoming medium dense dark grey slightly silty, sandy angular to subangular, fine to coarse GRAVEL of limestone. Sand is fine to coarse.
		1.20	ENV	SPT 1.00-1.45 4/4/5/4/4/5 N=18		0.95		Very stiff brown silty, sandy slightly gravelly CLAY. Gravel is angular to subrounded, fine to coarse of sandstone and limestone. Sand is fine to coarse. Occasional lenses of fine to coarse sand.		
						1.50		Medium dense brown slightly clayey, slightly silty, sandy angular to subrounded, fine to coarse GRAVEL of sandstone. Sand is fine to coarse with occasional fragments of coal.		
				SPT 2.00-2.45 4/4/3/3/4/4 N=14				2		
				SPT 3.00-3.45 4/4/5/5/5/6 N=21		3.00			3	
									4	

Remarks

1. Hole location scanned with CAT.
2. Backfilled with arisings.
- 3.