



Dŵr Cymru  
Welsh Water

PLA0042451



#### LEGEND(Representative of most common features)

|  |                                                  |  |                                                       |
|--|--------------------------------------------------|--|-------------------------------------------------------|
|  | Foul chamber                                     |  | Outfall                                               |
|  | Surface water chamber                            |  | Lamphole                                              |
|  | Combined chamber                                 |  | Storm Overflow                                        |
|  | Combined sewer overflow                          |  | Rising main                                           |
|  | Special purpose chamber                          |  | Gravity sewer                                         |
|  | Treatment works                                  |  | Private sewer                                         |
|  | Pumping station                                  |  | Private sewer subject to Sect. 104 adoption agreement |
|  | Combined                                         |  | Private Sewer Transfer                                |
|  | Surface Water                                    |  | Lateral Drain                                         |
|  | Foul                                             |  | Inspection Chamber                                    |
|  | Former S24 sewers (for indicative purposes only) |  |                                                       |

#### Notes:

Whilst every reasonable effort has been taken to correctly record the pipe material of DCWW assets, there is a possibility that in some cases pipe material (other than Asbestos Cement or Pitch Fibre) may be found to be asbestos cement (AC) or Pitch Fibre (PF). It is therefore advisable that the possible presence of AC or PF pipes be anticipated and considered as part of any risk assessment prior to excavation.

Dŵr Cymru Cylfyngedig (the Company) gives this information as to the position of its underground apparatus by way of general guidance only and on the understanding that it is based on the best information available and is not warranted as to its correctness in reliance upon it in the event of excavations or other works made in the vicinity of the Company's apparatus. The error of location of apparatus is liable to vary and any excavations made without prior notice to the Company, or any works made in the vicinity of the Company's apparatus, are done so in accordance with statutory requirements of sections 103 and 109 of the Water Industry Act 1991 which is based upon the best information available and, in particular, but without prejudice to the generality of the foregoing, it should be noted that the records that are available to the Company may not disclose the existence of water mains, surface water drains, lateral drains or other apparatus and any excavation made without prior notice to the Company, or any works made in the vicinity of the Company's apparatus, are done so in accordance with statutory requirements of sections 103 and 109 of the Water Industry Act 1991 and the Company's liability is limited to the best information available and is not warranted as to its correctness.

Service pipes are not generally shown but their presence should be anticipated.

**EXACT LOCATIONS OF ALL APPARATUS  
TO BE DETERMINED ON SITE.**

Reproduced by permission of the Ordnance Survey on behalf of  
HMSSO. © Crown copyright and database right 2017.  
All rights reserved.  
Ordnance Survey Licence number 100019534

Map Ref: 328858,343225  
Map scale: 1:568  
Printed by: Jenkins Tegan  
Printed on: 06 Jun 2019