

Cerys Jones

From: Sharon Holman
Sent: 04 March 2019 13:18
To: planning_admin
Subject: P/2018/0887 - Remediation Strategy
Attachments: Gresford Phase 5 Remediation Strategy.pdf

Civ – 'contamination report' attached and below

From: Bob Cartwright [<mailto:robert.cartwright6@btinternet.com>]
Sent: 04 March 2019 11:24
To: Sharon Holman; 'Russell Griffiths'; 'Steve Griffin'
Subject: Phase 5 The Pavillion Gresford - Remediation Strategy

Morning Sharon,

Russell has asked me to forward the above to you, in basic terms, minor contamination was found around TP 504 .The rest of the site is clear.

The Remediation Strategy attached prepared by Betts Geo Ltd, deals with the collection and removal of contaminated material to a control tip. All tickets for receipt of the contaminated material will be saved for inspection and clean material deposited from elsewhere on the site will be used for replacement in this area.

I understand that the above and enclosed information will satisfy your requirements.

Kind regards

Bob