

P/2016/0953 - Robinwood Activity Centre, Cross Lanes, Wrexham
Site Supervision Photographs - 26/07/2017



Photo 1 - Tree protective fencing erected along western edge of main access road in accordance with Tree Protection Plan (TPP)



Photo 2 - Tree protective fencing either side of access road



Photo 3 - Heras fence panels supported in plastic footing and fixed firmly in place by steel pins driven into the ground. Each panel is connected by anti-taper bolts and cannot be moved



Photo 3 - Steel pins driven 500mm into ground through support feet



Photo 5 - Tree protective fencing erected in front of G8



Photo 6 - Tree protective fencing erected around T11



Photo 7 - Tree protective fencing erected around T18 as per TPP



Photo 8 - Tree protective fencing erected around T21-T24



Photo 9 - Sand laid in preparation for installation of bog mat ground protection between building and T22/T24



Photo 10 - Tree protective fencing erected around T24/G10



Photo 11 - Tree protective fencing erected around T25, G12, W1b



Photo 12 - Tree protective fencing erected around proposed spoil mound area in SE corner of site. Mound located outside RPA of trees and a 1.5/2m easement is to be retained between the mound and fence along eastern boundary



Photo 13 - Tree protective fencing erected around T30-32 & W1 from access of internal road



Photo 14 - Ground protection (steel plates) installed between T30 & 32 as per AMS



**Photo 15 - Steel plate ground protection laid upon compressible layer of sand.
Type 1 roadstone laid around edge of boards - section towards T32 to be removed**



Photo 16 - Tree protective fencing erected around T1 to prevent soil mounding within RPA



Photo 17 - Tree protective fencing erected around G13 & G14 - protection during excavation of lake



Photo 18 - Tree protective fencing erected around TG14




Photo 19 - Tree protective Area sign erected at 10m intervals on fencing