



Appendix C3

Bulk Earthworks Documentation – Asbestos Hot Spot Delineation Photographs (During Bulk Earthworks)



Figure 1: 2141209_133216: Area quarantined and undergoing inspection



Figure 2: P1180021: Fragment of cement bonded asbestos prior to removal by litter-picking



Figure 3: P1180023: Suspect fibrous material



Figure 4: P1190030: Fragment of Asbestos Insulation Board (AIB) prior to removal by litter-picking



Figure 5: P1190031: Fragment of cement bonded asbestos prior to removal by litter-picking