



OUTSIDE SHED EARLY IN 2015 BEFORE WORK STARTED



INSIDE SHED SAME TIME



PICTURE BEFORE TOILET BLOCK CAME DOWN



NEW ROOF / SMOKE VENTS / CHIMNEY / TOILET BLOCK REMOVED



SEWAGE CONNECTIONS / SPOIL IN PILE WAITING FOR BUND



END VIEW OF SITE SHOWING RETAINING WALL.



END OF SITE WAITING FOR RETAINING WALL TO BE COMPLETE)



BOND READY TO RECEIVE SOIL / MAKE RECYCLED BLOCKS IN WALL



ROAD SIDE OF SHED SHOWING RECYCLED BLOCKS



RETAINING WALL FINISHED ON BACK OF SHED



FILLING BUND



AWAITING TO BE CAPED



BUND CARPED OFF



COMPRESSING SPOIL WITH WALKER PLATE



BUILDING PLATFORM IN FRONT OF BUND



WELSH SLATE FRONT AS ORIGINAL.



SHED AS AT 26TH SEPT 2015





WORK SHOP END



MUSEUM